



- LEGEND**
- ★ LNP Site
 - 8-km (5-mi.) Radius from Site
 - 1-km (0.6-mi.) Radius from Site
 - ▲ Levy Lithological Logs
 - Postulated Faults
Ticks indicate downthrown side.
(Source: Vernon, 1951)
 - Regional Fractures
(Source: Vernon, 1951)

Basemap: 1949 Aerial Photo (USDA, 1949)

0 2 4
Kilometers

0 1 2
Miles

Duke Energy Florida
**Levy Nuclear Plant
 Units 1 and 2**
Part 2, Final Safety Analysis Report

Vernon Fractures and Postulated Faults
 within the LNP Site Area Shown on
 1949 Aerial Photograph Mosaic
 FIGURE 2.5.3-208 Rev 6