| NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION | | | | |
|--|------------------------|---|--|-------------------|
| LICENSEE/LOCATION INSPECTED: Governor Juan F. Luis Hospital and Medical Center 4007 Estate Diamond Ruby Christiansted, St. Croix, Virgin Islands 00820 REPORT NUMBER(S) 2015001 | | NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713 | | |
| 3. DOCKET NUMBER(S) | 4. LICENSE NUMBER | | 5. DATE(S) OF INSPECTI | ION |
| 030-35612 LICENSEE: | 55- | 25547-01 | 2/25/15 | |
| The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X | | | | |
| | | pector will be t | aken to correct the violations identified. This tive steps already taken, corrective steps w | |
| | | | e to NRC will be required, unless specifical | |
| Title LICENSEE'S REPRESENTATIVE | Printed Name | | Signature | Date |
| NRC INSPECTOR | Robin Elliott | | /RA/ | 2/25/15 |
| BRANCH CHIEF | James Dwyer | | /RA/ | 3/9/15 |
| *NRC FORM 591M PART 1 (07-2012 |) (RI Rev. 09/12/2013) | 3:\WordDocs\0 | Current\Insp Record\R55-25547-01.2015-00 | 01.591M-Part1.doc |
| SUNSI Review Completed By: | / <i>RA</i> / RElliott | | x Public x | Non-Sensitive |