



Clinton Power Station  
8401 Power Road  
Clinton, IL 61727

U-604203  
March 23, 2015

10 CFR 50.55a(g)

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

Clinton Power Station, Unit 1  
Facility Operating License No. NPF-62  
NRC Docket No. 50-461

**SUBJECT:** Correction to C1R14 Post-Outage 90-Day Inservice Inspection (ISI) Summary Report

**Reference:** Letter from B. K. Taber (EGC) to NRC Document Control Desk, "Post-Outage 90-Day Inservice Inspection (ISI) Summary Report," dated January 28, 2014 (ML14031A222)

In the referenced letter, Exelon Generation Company (EGC) submitted the Post-Outage (90-Day) ISI Summary Report for Clinton Power Station, Unit 1, for examinations and repair/replacement activities performed between December 23, 2011 (i.e., end of the 13<sup>th</sup> refueling outage) and October 30, 2013 (i.e., end of the 14<sup>th</sup> refueling outage). This letter corrects some typographical errors in that document. The attachment contains the replacement pages for the referenced report.

This letter contains no regulatory commitments.

Please direct any questions you may have regarding this submittal to Mr. Jeffrey Cunningham, Regulatory Assurance Manager, at (217) 937-3160.

Respectfully,

A handwritten signature in black ink, appearing to read "Mark M. Newcomer", written over a printed name.

Mark M. Newcomer  
Site Vice President  
Clinton Power Station

JLP/cas

**Attachment:** Revised Pages for the Clinton Power Station, Inservice Inspection Summary Report

**cc:** Regional Administrator, NRC Region III  
NRC Senior Resident Inspector – Clinton Power Station  
Office of Nuclear Facility Safety – IEMA Division of Nuclear Safety

A047  
NRR

## **Attachment**

### **Revised Pages for the Clinton Power Station, Inservice Inspection Summary Report**

- 1. Replacement page for Attachment 1, Table 1 (second page)**
- 2. Replacement page for Attachment 2, first page**



# FORM NIS-1 OWNER'S REPORT FOR INSERVICE INSPECTION

## ATTACHMENT 2

- |  |   |
|--|---|
| 1. Owner: <u>Exelon Nuclear, 4300 Winfield Road, Warrenville, IL 60555</u> |   |
| 2. Plant: <u>Clinton Power Station, 8401 Power Rd., Clinton, IL 61727</u>  |   |
| 3. Plant Unit: <u>1</u>  | 4. Owner Certificate of Authorization: <u>N/A</u> |
| 5. Commercial Service Date: <u>4-24-87</u>                                 | 6. National Board Number for Unit: <u>N/A</u>     |

### 15. Abstract of Examinations:

#### **Examinations:**

#### **IRM "C" (22-35) and IRM "E" (30-27) –**

During this outage, C1R14, cracking was observed on Dry Tube IRM "C" (22-35) and IRM "E" (30-27).

Corrective Measures – Clinton Power Station has evaluated these cracking and justified continued operation.

#### **LPRM 14-47 and LPRM 38-31 –**

During this outage, C1R14, blockage was observed in all four (4) of the lower holes on LPRM 14-47 and 38-47.

Corrective Measures – Clinton Power Station has evaluated the blockage and justified continued operation.

#### **SRM "C" (30-19) and SRM "D" (38-35) –**

During this outage, C1R14, cracking was observed on Dry Tube SRM "C" (30-19) and SRM "D" (38-35).

Corrective Measures – Clinton Power Station has evaluated these cracking and justified continued operation.