



**Legend**


• Failed MIT Wells 160 & 180 sd	— Monitor Ring	— Permit 633
— Wellfield Patterns	— Permit 603	— Reynolds
	— Sections	



REVISIONS		
NO.	DATE	BY


 Cameco Resources  
 762 Ross Road  
 Douglas, WY 82633  
 Telephone: (307) 358-6541

**E Wellfield**  
**T36N R73W**  
**160 & 180 Sands**  
**Plate 3F**

  
 1" = 500'

X 3/12/2015 XXXX  
© 2015 Cameco Resources. All rights reserved. This document is the property of Cameco Resources and is not to be distributed, copied, or reproduced without the written permission of Cameco Resources.