


Legend


• Failed MIT Wells No Sand Impacted	Permit 603	Sections
Wellfield Patterns	Permit 633	Reynolds
Monitor Ring		



REVISIONS		
NO.	DATE	BY

Cameco
 Cameco Resources
 762 Ross Road
 Douglas, WY 82633
 Telephone: (307) 358-6541

**C Wellfield
 T36N R73W
 No Sand Interval
 Plate 2G**



DATE PLOTTED: 3/12/2015 11:05 AM
 USER: XXXX
 PROJECT: T36N R73W No Sand Interval Plate 2G
 SHEET: 2G-2015.mxd