




R0 (North)



Crawford Basin Geologic Structure



Cameco Resources
Cameco
 Crow Butte Operation
 Cross Section R0 - R0'

Date: September 2015
 Department: Land & Evaluation
 Vertical Exaggeration = 10X

Figure 2.6-22
 1002