



R1' (North)

R1' (South)



Crawford Basin Geologic Structure



Camenco Resources
Camenco
 Crow Butte Operation
 Cross Section R1 - R1'

Figure 2.6-23
 103

Date: SEPTEMBER 2015
 Department: Land & Evaluation
 Vertical Exaggeration = 10X