



— flashboard failure at 2 ft. no flashboard failure

WLS COL 2.4-2

WILLIAM STATES LEE III NUCLEAR STATION UNITS 1 & 2	
Discharge Rating Curve, Gaston Shoals Dam	
FIGURE 2.4.3-212	Rev 0