

Duke Energy Florida
Levy Nuclear Plant
Units 1 and 2
Part 2, Final Safety Analysis Report

Summary of Hydrologic Soil Groups in the Withlacoochee River Drainage Basin
FIGURE 2.4.3-210
Rev 6