

Duke Energy Florida
Levy Nuclear Plant
Units 1 and 2
Part 2, Final Safety Analysis Report

Radwaste / Annex Building Subgrade

FIGURE 2.5.4.8-204 Rev. 6