

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:

Soils & Structures, Inc  
6480 GRAND HAVEN Rd  
Muskegon, MI

2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

REPORT NUMBER(S) 2015001

3. DOCKET NUMBER(S)

030- 33048

4. LICENSE NUMBER(S)

21-26469-01

5. DATE(S) OF INSPECTION

12/2/15

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	E.L. Kulzer		12/2/15
BRANCH CHIEF	Aaron T. McGowan		12/14/15

**Docket File Information**

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  Soils & Structures, Inc. 6480 Grand Haven Rd. Muskegon, MI 49424  REPORT NUMBER(S) 2015001	2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S)  030-33048	4. LICENSE NUMBER(S)  21-26469-01	5. DATE(S) OF INSPECTION  12/02/2015
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED  IP 87124	7. INSPECTION FOCUS AREAS  03.01 through 03.07
---	--

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)  03121	2. PRIORITY  5	3. LICENSEE CONTACT  Jon Erickson	4. TELEPHONE NUMBER  (800) 933-3959
---------------------------------	----------------------	---	---

Main Office Inspection      Next Inspection Date: 12/03/2020

Field Office Inspection \_\_\_\_\_

Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

This was a routine unannounced inspection of an engineering firm located in Muskegon, Michigan. At this location the licensee possessed 15 portable gauges for use during the construction season (May-November) for soils engineering projects. The licensee employed twenty authorized gauge users who have completed approved training on these gauges. The licensee stored its gauge inside a locked storage room with a locked door at the licensee's facility.

**Performance Observations**

At the time of this inspection, the gauges were in use. An authorized gauge user was interviewed by the inspector and possessed required shipping papers that contained all appropriate information and were accessible in the transport vehicle. The licensee locked and chained its gauge to the rear of the vehicle during transport. The authorized gauge user demonstrated an adequate level of understanding of emergency and handling procedures. The authorized user described security during transport with no problems noted. The inspector reviewed other program areas which included dosimetry, 20.1101 audits, leak tests, inventory checks, and survey instrument availability.

No violations of NRC regulatory requirements were identified during this inspection.