



— flashboard failure at 2 ft.    ..... no flashboard failure

WLS COL 2.4-2

WILLIAM STATES LEE III  
 NUCLEAR STATION UNITS 1 & 2  
 Discharge Rating Curve, Gaston Shoals Dam  
 FIGURE 2.4.3-212    Rev 0