

FIG 7.2-1a
NUCLEAR BOILER SYSTEM PIPING AND INSTRUMENTATION DIAGRAM
NINE MILE POINT NUCLEAR STATION - UNIT 2
NIAGARA MOHAWK POWER CORPORATION
PRELIMINARY SAFETY ANALYSIS REPORT

D