



FIG. 5.3-2
 STAND-BY GAS TREATMENT SYSTEM
 NINE MILE POINT NUCLEAR STATION UNIT 2
 NIAGARA MOHAWK POWER CORPORATION
 PRELIMINARY SAFETY ANALYSIS REPORT

D