



PEACH BOTTOM ATOMIC POWER STATION  
UNITS 2 AND 3  
UPDATED FINAL SAFETY ANALYSIS REPORT

Clamps installed on the replacement core spray  
sparger pipes structurally replacing welds at each of  
the four sparger T-box locations