# CATEGORY 3

#### REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBP:9907260014 DOC.DATE: 99/06/30 NOTARIZED: NO DOCKET # FACIL:50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylva 05000387 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylva 05000388 AUTHOR AFFILIATION · AUTH.NAME YOUNG, K.A. Pennsylvania Power & Light Co. SAUNDERS, R.F. Pennsylvania Power & Light Co. RECIPIENT AFFILIATION RECIP. NAME SUBJECT: Monthly operating repts for June 1999 for Susquehanna Steam Electric Station, Units 1 & 2. With 990709 ltr. DISTRIBUTION CODE: IE24D COPIES RECEIVED:LTR ENCL SIZE: TITLE: Monthly Operating Report (per Tech Specs) NOTES: 05000387 COPIES RECIPIENT RECIPIENT COPIES LTTR ENCL ID CODE/NAME ID CODE/NAME LTTR ENCL NERSES, V 1 1 1 INTERNAL: ACRS 1 FILE CENTER 01 OC/DBA/PAD 1 1 RES/DRAA/OERAB 1 RGN1 1 1 EXTERNAL: LMITCO MARSHALL 1 1 NOAC 1 1 NRC PDR 1 1 NOTES: 1 1



NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 10 ENCL 10

C

A

T

E

G

0

R

Y

1

D

0

C

U

M

Έ

N

T

# Robert F. Saunders Vice President - Nuclear Site Operations

#### Susquehanna Steam Electric Station. P.O. Box 467, Berwick, PA 18603 Tel. 717.542.3256 Fax 717.542.1504 rfsaunders@papl.com



July 9, 1999

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Station P1-137 Washington, D.C. 20555

SUSQUEHANNA STEAM ELECTRIC STATION
MONTHLY OPERATING REPORTS Docket Nos. 50-387/NPF-14
and 50-388/NPF-22
PLA - 0005087 FILE: R41-2A

The June 1999 monthly operating reports for Susquehanna SES Units 1 and 2 are attached.

Very truly yours,

Robert F. Saunders

/cmm

cc: NRC Region 1

NRC Sr. Resident Inspector, Mr. S. Hansell NRC Sr. Project Manager, Mr. V. Nerses

IEZY

9907260014 990630 PDR ADDCK 05000387

# File R41-2A PLA- 0005087 Document Control Desk


bc:

INPO Records Center 700 Galleria Parkway Atlanta, GA 30339-5957 American Nuclear Insurers Town Center, 300S 29 South Main Street West Hartford, Ct 06107-2445

Attn: Mr. Stanley Focht

Mr. S. Maingi
Department of Environmental Protection
Bureau of Rad Protection
P.O. Box 2063
Harrisburg, PA 17102

| R. G. Byram             | GENTW16        |
|-------------------------|----------------|
| R. R. Wehry             | NUCSA4         |
| H. D. Woodeshick        | Special Office |
| K. A. Young             | NUCSA2         |
| Licensing Corresp. File | GENA61         |
| Nuclear Records File    | GENA62         |
| DCS File                | NUCSA2         |
|                         |                |



## **OPERATING DATA REPORT**



 DOCKET NO.
 50-387

 UNIT
 One

 DATE
 7/8/99


 COMPLETED BY
 K. A. Young

 TELEPHONE
 (717) 542-3251

## **OPERATING STATUS**

| 1. | Unit Name: Susquehanna Steam Elec      | tric Station (U1) | te .      |             |
|----|--|-------------------|-----------|-------------|
| 2. | Reporting Period: June 1999            |                   |           |             |
| 3. | Design Electrical Rating (Net MWe):    | 1100              | •         |             |
| 4. | Maximum Dependable Capacity (Net MWe): | 1090              | •         |             |
|    | •                                      | This Month        | Yrto-Date | Cumulative  |
| 5. | Hours in Reporting Period              | 720               | 4,343     | 140,808     |
| 6. | Number of Hours Reactor Was Critical   | 625.4             | 4193.8    | 113,802.7   |
| 7. | Hours Generator On-Line                | 602.2             | 4170.3    | 111,779.1   |
| 8. | Unit Reserve Shutdown Hours            | 0                 | 0         | 0           |
| 9. | Net Electrical Energy Generated (MWH)  | 592,624           | 4,403,828 | 113,229,575 |

# **NOTES:**



# ANNA STATE S

#### **UNIT SHUTDOWNS**

 DOCKET NO.
 50-387

 UNIT
 One

 DATE
 7/8/99

 COMPLETED BY
 K. A. Young

 TELEPHONE
 (717) 542-3251

REPORT MONTH June 1999

| No. | Date    | Type <sup>t</sup> | Duration<br>(Hours) | Reason <sup>2</sup> | Method of<br>Shutting<br>Down<br>Reactor <sup>3</sup> | Cause & Corrective Action To Prevent Recurrence  |
|-----|---------|-------------------|---------------------|---------------------|---|--|
| 1   | 5-29-99 | F.                |                     | A                   | 4   | (Continuation of Forced Outage from 5-29-99) Turbine control valve failed surveillance testing due to a fast acting solenoid valve problem. Unit was taken off-line at 17:04 hours and Reactor was manually scrammed at 17:24 hours. Maintenance activities included replacement of these solenoid valves on all Turbine control valves and main steam bypass valves. Unit returned to service on June 5 at 21:50 hours and reached 100% at 0700 hours June 9th. |

Summary: Unit one experienced a downpower to 75% on June 16<sup>th</sup> to repair internal tube leaks in the 3A Feedwater heater. Unit returned to full power on June 19th

F. Forced

S. Scheduled

2.

Reason:

- A Equipment Failure (Explain)
- B Maintenance or Test
- C Refueling
- D Regulatory Restriction

E – Operator Training & Licensee

Exam

F - Administrative

G - Operational Error (Explain)

3.

#### Method:

- 1 Manual
- 2 Manual Scram
- 3 Automatic Scram
- 4 Continuation from previous month
- 5 Other

Page 1 of 1

#### SUSQUEHANNA STEAM ELECTRIC STATION

Docket Number: <u>50-387</u> Completed by: <u>K.A. Young</u>

Date:

Telephone:

Challenges to Main Steam Safety Relief Valves

None.

Major Changes to Radioactive Waste Treatment System

None.

;· ; • . d tr , • ą **V** 

# OPERATING DATA REPORT



 DOCKET NO.
 50-388

 UNIT
 Two

 DATE
 7/8/99

 COMPLETED BY
 K. A. Young

 TELEPHONE
 (717) 542-3251

# **OPERATING STATUS**

| 1.        | Unit Name: Susquehanna Steam Elec      | tric Station (U2) |           |             |
|-----------|--|-------------------|-----------|-------------|
| <u>2.</u> | Reporting Period: June 1999            |                   |           | •           |
| 3.        | Design Electrical Rating (Net MWe):    | 1100              |           | 4           |
| 4.        | Maximum Dependable Capacity (Net MWe): | 1094              |           |             |
|           |  |                   |           |             |
|           | ,                                      | This Month        | Yrto-Date | Cumulative  |
| 5.        | Hours in Reporting Period              | 720               | 4,343     | 126,047     |
| 6.        | Number of Hours Reactor Was Critical   | 559.9             | 3138.3    | 107,020     |
| 7.        | Hours Generator On-Line                | 529.9             | 3013.2    | 105,228.4   |
| 8.        | Unit Reserve Shutdown Hours            | 0                 | 0         | 0           |
| 9.        | Net Electrical Energy Generated (MWH)  | 559,120           | 3.170.979 | 108.436.795 |

### **NOTES:**



#### **UNIT SHUTDOWNS**

DOCKET NO. <u>50-388</u>
UNIT <u>Two</u>
DATE <u>7/8/99</u>
COMPLETED BY <u>K. A. Young</u>
TELEPHONE <u>(717) 542-3251</u>

| REPORT MONTH | June 1999 |
|--------------|-----------|
|              |           |

| No. | Date   | Туре | Duration<br>(Hours) | Reason <sup>2</sup> | Method of Shutting Down Reactor | Cause & Corrective Action to Prevent Recurrence   |
|-----|--------|------|---------------------|---------------------|---------------------------------|---|
| 3   | 6/8/99 | F    | 190.2               | A                   | 3                               | Unit Two experienced an autoscram at 12:06 hours June 8th. Failure of the 2A main transformer resulted in a load reject and autoscram. A seven day forced outage was entered with maintenance activities for: replacement of the main transformer, repairs on the acoustic monitors and loose parts detectors, and replacement of fast acting solenoids on the main turbine bypass valves. Unit returned to service on June 16th. |

Unit Two power ascension was placed on hold for 18 hours on June 17 for feedwater flow balance problems with the "C" feedwater pump

1.

F. Forced

S. Scheduled

2.

Reason

A - Equipment Failure (Explain)

B - Maintenance or Test

C - Refueling

D - Regulatory Restriction

E - Operator Training & Licensee

Exam

F - Administrative

G - Operational Error (Explain)

3.

Method:


1 - Manual

2 - Manual Scram

3 - Automatic Scram

4 - Continuation from previous month

5 - Other



#### SUSQUEHANNA STEAM ELECTRIC STATION

Docket Number: 50-388

Date:

7/8/99

Completed by: K. A. Young

Telephone:

(717) 542-3251

# Challenges to Main Steam Safety Relief Valves

Unit Two experienced an automatic reactor scram from 100% power at 1206 hours June 8. Two safety relief valves lifted to control peak reactor pressure. Data for SRV actuations is listed below. Each valve reseated after the transient.

| <u>SRV</u> | Length of Time O (sec) | <u>pen</u> | Pressure at Lift (psi) | Pressure at Close (psi) |
|------------|------------------------|------------|------------------------|-------------------------|
| L          | 11                     | •          | 1098                   | 991                     |
| M          | 11                     |            | 1098                   | 991                     |

Major Changes to Radioactive Waste Treatment System

None.

, • 

· Sugar