

27-11-1960

1. The first part of the report is devoted to a description of the

1. The first part of the report is devoted to a description of the

1. The first part of the report is devoted to a description of the



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

October 3, 1988

Mr. Robert A. Gadinski
Hydrogeologist
Bureau of Water Quality Management
Pennsylvania Department of Environmental Resources
90 E. Union Street, 2nd Floor
Wilkes-Barre, PA 18701

SUSQUEHANNA STEAM ELECTRIC STATION
SULFURIC ACID LEAK
CCN 591336 FILE R9-8C
PLE-10887

Dear Mr. Gadinski:

At your request, I am informing you of the well water sample parameters that we will analyze for in association with the sulfuric acid pipe leak remediation. The parameters will be pH, primary drinking water metals, and sulfates.

If you have any questions, please contact me at (215) 770-7887.

Respectfully,

John B. Hansell, Jr.
Environmental Scientist

cc: ~~Dr. W. R. Butler~~ NRC
K. Augustine Pa DER
R. Lewis Pa DER

Cool
1/0

8810070347 881003
PDR ADOCK 05000337
P FDC