

Hematite Decommissioning Project	Procedure: HDP-PR-FSS-701, Final Status Survey Plan Development		
		Revision: 9	Appendix P-6, Page 1 of 3

**APPENDIX P-6  
FSS FIELD LOG**

**Survey Area:** PSA 01                      **Description:** Piping Survey Area Bldg 110 SE (STM-2)  
**Survey Unit:** 02                              **Description:** Storm Water Piping SE of Bldg 110

**FSS Field Log:**

<b><u>Date/Time:</u></b>	<b><u>Observation or Comment:</u></b>	<b><u>Technician</u></b>
2/4/16 – 14:15	Pre-QC check of 2360/43-68 Z	J. Michel
2/4/16 – 14:26	Instrument put into pipe for survey	J. Michel
2/4/16 – 14:27	Background #1 taken at waist level in MH 25	J. Michel
2/4/16 – 14:28	Background #2 taken at waist level in MH 25	J. Michel
2/4/16 – 14:29	Background #3 taken at waist level in MH 25	J. Michel
2/4/16 – 14:33	Instrument placed at the bottom of MH 25 at 101' for Systematic P01-02-06-S-O-S-00	J. Michel
2/4/16 – 14:36	Begin survey of pipe heading West to MH 06 at 1"-2" per second	J. Michel
2/4/16 – 14:39	Systematic P01-02-05-S-O-S-00 taken	J. Michel
2/4/16 – 14:41	Biased reading #1 taken at a seam	J. Michel
2/4/16 – 14:45	Systematic P01-02-04-S-O-S-00 taken	J. Michel
2/4/16 – 14:47	Sled arrives at MH 06	J. Michel
2/4/16 – 14:48	Biased reading #2 taken at the bottom of MH 06	J. Michel
2/4/16 – 14:50	Instrument taken out of MH 06	J. Michel
2/4/16 – 15:06	Instrument placed into pipe mode again to begin counting	J. Michel
2/4/16 – 15:08	Instrument placed back into normal mode to stop counting	J. Michel
2/4/16 – 15:16	Instrument placed into pipe mode in MH 25 again to begin survey	J. Michel
2/4/16 – 15:17	Begin pulling instrument sled 1" – 2" per second from MH 25 to MH 09	J. Michel
2/4/16 – 15:21	Systematic P01-02-07-S-O-S-00 taken	J. Michel
2/4/16 – 15:23	Biased reading #3 taken at seam 20' from MH 25 going East	J. Michel
2/4/16 – 15:27	Systematic P01-02-08-S-O-S-00 taken	J. Michel
2/4/16 – 15:29	Biased reading #4 taken at seam 8' from MH 09	J. Michel
2/4/16 – 15:31	Reached MH 09. Take instrument out of hole	J. Michel
2/4/16 – 16:00	Post QC check of 2360/43-68 Z	J. Michel
	Survey log number – 6980 C 160204	



