

**APPENDIX P-6
FSS FIELD LOG**

Survey Area: PSA 01 **Description:** Piping Survey Area Bldg 230 S (STM-9)

Survey Unit: 09 (STM-9) **Description:** Storm Water Piping S of Bldg 230

FSS Field Log: Systematic Survey

<u>Date/Time:</u>	<u>Observation or Comment:</u>	<u>Technician</u>
12/3/15 – 08:41	Pre-QC check of Ludlum 2360/43-68 Z on sled.	G. Peterschmidt
12/3/15 – 09:41	Background #1 taken in MH 01 at waist level.	G. Peterschmidt
12/3/15 – 09:42	Background #2 taken in MH 01 at waist level.	G. Peterschmidt
12/3/15 – 09:43	Background #3 taken in MH 01 at waist level.	G. Peterschmidt
12/3/15 – 09:48	2360/4368 sled placed in 18” pipe.	G. Peterschmidt
12/3/15 – 09:51	Begin sled pull from MH 01 East towards MH 22	G. Peterschmidt
12/3/15 – 09:54	P01-09-01-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 09:59	P01-09-02-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 10:04	P01-09-03-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 10:08	P01-09-04-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 10:13	P01-09-05-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 10:18	P01-09-06-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 10:23	P01-09-07-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 10:28	P01-09-08-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 10:32	P01-09-09-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 10:38	P01-09-10-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 10:45	P01-09-11-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 10:50	P01-09-12-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 10:55	P01-09-13-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 11:00	P01-09-14-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 11:05	P01-09-15-S-O-S-00 reading taken	G. Peterschmidt
12/3/15 – 11:08	2360/43-68 sled taken out of pipe at end of run. MH 22 has been previously removed.	G. Peterschmidt
12/3/15 – 14:20	Post-QC check of Ludlum 2360/43-68 Z on sled.	G. Peterschmidt

Survey Area: PSA 01 **Description:** Piping Survey Area Bldg 230 S (STM-9)

**APPENDIX P-6
FSS FIELD LOG**

Survey Unit: 09 (STM-9)

Description: Storm Water Piping S of Bldg 230

FSS Field Log: Biased Survey

<u>Date/Time:</u>	<u>Observation or Comment:</u>	<u>Technician</u>
12/3/15 – 13:12	Mid-day QC check of Ludlum 2360/43-68 Z on sled.	G. Peterschmidt
12/3/15 – 13:31	Background #1 taken in MH 01 at waist level.	G. Peterschmidt
12/3/15 – 13:32	Background #2 taken in MH 01 at waist level.	G. Peterschmidt
12/3/15 – 13:33	Background #3 taken in MH 01 at waist level.	G. Peterschmidt
12/3/15 – 13:34	2360/4368 sled placed in 18” pipe.	G. Peterschmidt
12/3/15 – 13:35	Begin sled pull from MH 01 East towards MH 22	G. Peterschmidt
12/3/15 – 13:36	Biased reading #1 taken at 25’, downspout	G. Peterschmidt
12/3/15 – 13:40	Biased reading #2 taken at 67’	G. Peterschmidt
12/3/15 – 13:43	Biased reading #3 taken at 88’, Building drain	G. Peterschmidt
12/3/15 – 13:46	Biased reading #4 taken at 106’, downspout	G. Peterschmidt
12/3/15 – 13:49	Biased reading #5 taken at 145’, downspout	G. Peterschmidt
12/3/15 – 13:55	Biased reading #6 taken at 187’, downspout	G. Peterschmidt
12/3/15 – 13:57	Biased reading #7 taken at 190’, 45 degree bend	G. Peterschmidt
12/3/15 – 14:03	Instrument out of pipe	G. Peterschmidt