

## UNITED STATES NUCLEAR REGULATORY COMMISSION

**REGION II** 

245 PEACHTREE CENTER AVENUE NE, SUITE 1200 ATLANTA, GEORGIA 30303-1257

August 28, 2017

Mr. Darin J. Myers Site Vice President Southern Nuclear Operating Company, Inc. Vogtle Electric Generating Plant 7821 River Road Waynesboro, GA 30830

SUBJECT: UPDATED INSPECTION PLAN FOR VOGTLE ELECTRIC GENERATING PLANT

UNITS 1 AND 2 - NRC REPORT 05000424/2017005 AND 05000425/2017005

Dear Mr. Myers:

The enclosed inspection plan lists the inspections scheduled through June 30, 2019 for Vogtle Electric Generating Plant, Units 1 and 2. The NRC provides the inspection plan to allow for the resolution of any scheduling conflicts and personnel availability issues. Routine inspections performed by resident inspectors are not included in the inspection plan. The inspections listed during the last twelve months of the inspection plan are tentative and may be revised. The NRC will contact you as soon as possible to discuss changes to the inspection plan should circumstances warrant any changes. This inspection plan does not include the plan for security-related inspections, which will be sent via separate, non-publicly available correspondence.

Also, on August 28, 2017, the NRC began the Supplemental Inspection (IP 95001) for a White finding associated with the failure to maintain a standard emergency classification scheme. Specifically, the emergency classifications RG1 & RS1 contained effluent radiation monitor threshold values significantly different than appropriate.

In accordance with Title 10 of the *Code of Federal Regulations* (10 CFR) 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a> (the Public Electronic Reading Room).

D. Myers 2

Please contact me at (404) 997-4513 with any questions you have regarding this letter.

Sincerely,

/RA/

Shane R. Sandal, Chief Reactor Projects Branch 2 Division of Reactor Projects

Docket Nos.: 50-424, 50-425 License Nos.: NPF-68 and NPF-81

Enclosure: Vogtle Inspection/Activity Plan 08/01/2017-06/30/2019

Distribution via Listserv

D. Myers 3

SUBJECT: UPDATED INSPECTION PLAN FOR VOGTLE ELECTRIC GENERATING PLANT

UNITS 1 AND 2 - NRC REPORT 05000424/2017005 AND 05000425/2017005

August 28, 2017

#### **DISTRIBUTION:**

M. Kowal, RII
K. Sloan, RII
OE Mail
RIDSNRRDIRS
PUBLIC
RidsNrrPMVogtleResource
ROP Assessment
ROP Reports
Institute of Nuclear Power Operations (INPO)

#### ADAMS Accession Number: ML17240A082

OFFICE	RII:DRP	RII:DRP		
NAME	DMas	SSandal		
DATE	8/23/2017	8/25/2017		

**OFFICIAL AGENCY RECORD** 

# Vogtle Inspection / Activity Plan 08/01/2017 - 06/30/2019

Unit	Planne	ed Dates	]		No. of Staff
Number	Start	End	Inspection Activ	Title Title	on Site
			95001 - V0	OGTLE 95001 INSPECTION	4
1, 2	08/28/2017	09/01/2017	IP 95001	Supplemental Inspection for One or Two White Inputs in a Strategic Performance Area	
			ISI - UI	NIT 2 IN-SERVICE INSPECTION	1
2	09/25/2017	09/29/2017	IP 7111108P	Inservice Inspection Activities - PWR	
			RP - RI	P PUBLIC INSPECTION	2
1, 2	09/25/2017	09/29/2017	IP 71124.01	Radiological Hazard Assessment and Exposure Controls	
1, 2	09/25/2017	09/29/2017	IP 71124.08	Radioactive Solid Waste Processing and Radioactive Material Handling, Storage, and Transportation	
			OL EXAM - IN	ITIAL LICENSE EXAM	4
1	10/06/2017	10/17/2017	V23491	VOGTLE/UNIT 1 APRIL 2017 INITIAL EXAM AT POWER FACILITIES	
			EQI - DI	ESIGN BASES ASSURANCE INSPECTION (PROGR	4
1, 2	11/06/2017	11/10/2017	IP 7111121N	Design Bases Assurance Inspection (Programs)	
1, 2	11/27/2017	12/01/2017	IP 7111121N	Design Bases Assurance Inspection (Programs)	
1, 2	12/11/2017	12/15/2017	IP 7111121N	Design Bases Assurance Inspection (Programs)	
			TI-191 - M	TIGATING STRATEGIES	4
1, 2	11/13/2017	11/17/2017	IP 2515/191	Inspection of Licensee's Responses to Order EA-12-049, EA-12-051 & EP Info Request March 12, 2012	
			RP - RI	P PUBLIC INSPECTION	2
1, 2	12/04/2017	12/08/2017	IP 71124.06	Radioactive Gaseous and Liquid Effluent Treatment	
1, 2	12/04/2017	12/08/2017	IP 71124.07	Radiological Environmental Monitoring Program	
1, 2	12/04/2017	12/08/2017	IP 71151	Performance Indicator Verification	
			EP - EI	PEXERCISE	6
1, 2	05/14/2018	05/18/2018	IP 7111401	Exercise Evaluation	
1, 2	05/14/2018	05/18/2018	IP 7111404	Emergency Action Level and Emergency Plan Changes	
1, 2	05/14/2018	05/18/2018	IP 7111408	Exercise Evaluation – Scenario Review	
1, 2	05/14/2018	05/18/2018	IP 71151-EP02	ERO Readiness	
			MODS - PI	ANT MODIFICATIONS INSPECTION	3
1, 2	08/27/2018	08/31/2018	IP 7111117T	Evaluations of Changes, Tests, and Experiments	
			ISI - UI	NIT 1 IN-SERVICE INSPECTION	1
1	09/24/2018	09/28/2018	IP 7111108P	Inservice Inspection Activities - PWR	
			RP - RI	OCCUPATIONAL - WEEK 1	2
1, 2	09/24/2018	09/28/2018	IP 71124.01	Radiological Hazard Assessment and Exposure Controls	
1, 2	09/24/2018	09/28/2018	IP 71124.02	Occupational ALARA Planning and Controls	
1, 2	09/24/2018	09/28/2018	IP 71124.03	In-Plant Airborne Radioactivity Control and Mitigation	
1, 2	09/24/2018	09/28/2018	IP 71124.04	Occupational Dose Assessment	

This report does not include INPO and OUTAGE activities. This report shows only on-site and announced inspection procedures.

### Vogtle Inspection / Activity Plan 08/01/2017 - 06/30/2019

Unit		d Dates				No. of Staff			
Number	Start	End	Inspection Ac	ctivity	Title	on Site			
	RP - RP OCCUPATIONAL - WEEK 1 2								
1, 2	09/24/2018	09/28/2018	IP 71151-OR0	01	Occupational Exposure Control Effectiveness				
1, 2	09/24/2018	09/28/2018	IP 71151-PR0	01	RETS/ODCM Radiological Effluent Occurrences				
			SGISI -	- UNIT 1 :	SG IN-SERVICE INSPECTION	1			
1	09/24/2018	09/28/2018	IP 7111108P		Inservice Inspection Activities - PWR				
			RP -	- RP OCC	CUPATIONAL - WEEK 2	2			
1, 2	10/15/2018	10/19/2018	IP 71124.01		Radiological Hazard Assessment and Exposure Controls				
1, 2	10/15/2018	10/19/2018	IP 71124.02		Occupational ALARA Planning and Controls				
1, 2	10/15/2018	10/19/2018	IP 71124.03		In-Plant Airborne Radioactivity Control and Mitigation				
1, 2	10/15/2018	10/19/2018	IP 71124.04		Occupational Dose Assessment				
1, 2	10/15/2018	10/19/2018	IP 71151-OR0	01	Occupational Exposure Control Effectiveness				
1, 2	10/15/2018	10/19/2018	IP 71151-PR0	)1	RETS/ODCM Radiological Effluent Occurrences				
			OL EXAM -	- INITIAL	LICENSE EXAM PREP	3			
1	10/29/2018	11/02/2018	V23520		VOGTLE U1/ DECEMBER 2018 INITIAL EXAM AT POWER FACILITIES				
			OL EXAM -	- INITIAL	LICENSE EXAM	3			
1	11/26/2018	12/14/2018	V23520		VOGTLE U1/ DECEMBER 2018 INITIAL EXAM AT POWER FACILITIES				
			RP -	- RP INST	TRUMENTS	1			
1, 2	12/03/2018	12/07/2018	IP 71124.05		Radiation Monitoring Instrumentation				
			ISI -	- UNIT 2 I	IN-SERVICE INSPECTION	1			
2	03/18/2019	03/22/2019	IP 7111108P		Inservice Inspection Activities - PWR				
			RP -	- RP RAD	DHAZARDS	1			
1, 2	03/18/2019	03/22/2019	IP 71124.01		Radiological Hazard Assessment and Exposure Controls				
			SGISI -	- UNIT 2	SG IN-SERVICE INSPECTION	1			
2	03/18/2019	03/22/2019	IP 7111108P		Inservice Inspection Activities - PWR				
			PI&R -	- PROBL	EM IDENTIFICATION AND RESOLUTION	5			
1, 2	04/22/2019	04/26/2019	IP 71152B		Problem Identification and Resolution				
1, 2	05/06/2019	05/10/2019	IP 71152B		Problem Identification and Resolution				
			EP -	- EP PRO	OGRAM INSPECTION	3			
1, 2	05/06/2019	05/10/2019	IP 7111402		Alert and Notification System Testing				
1, 2	05/06/2019	05/10/2019	IP 7111403		Emergency Preparedness Organization Staffing and Augmentation System				
1, 2	05/06/2019	05/10/2019	IP 7111404		Emergency Action Level and Emergency Plan Changes				
1, 2	05/06/2019	05/10/2019	IP 7111405		Correction of Emergency Preparedness Weaknesses and Deficiencies				
1, 2	05/06/2019	05/10/2019	IP 71151		Performance Indicator Verification				

This report does not include INPO and OUTAGE activities. This report shows only on-site and announced inspection procedures.