

FEDERAL NOTIFICATION LETTER

Monday, August 21, 2017

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

GE Hitachi Nuclear Energy
1990 Little Orchard Street
San Jose CA 95125

To Specific Licensee:

SRB Technologies, Inc.
2580 Landmark Drive
Winston-Salem, NC 27103
(336)-659-2610
Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee)	10-23-2017
--	------------

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name:	PATRICK L. VANCE
Signature:	<i>Patrick L. Vance</i>
Phone Number:	408-497-6437

FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT

VEOLIA USE ONLY

SALES ORDER: 1886849

CASE: 33046

VEOLIA USE ONLY

RGA#: 996727

RGA# Exiration Date: 11/14/17

UCN: 1A51389B-6C54055D

FedEx Tracking #: 691191700755379

Box 1 of 1

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMAITON.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1. Exit Sign safety light	SLX-60	335204	8/2005	7.5
2. Exit sign Safety Sign	U10	82135	6/88	20
3. exit sign safety light	s1x-60	358354	2/06	7.5
4. exit sign safety light	s1x-60	358357	2/06	7.5
5.				
6.				
7.				
8.				
9.				
10.				

Describe any damaged units:
Please email pictures of damaged signs to
pak.ts@veolia.com

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

GENERATOR CERTIFICATION

Generator Signature:

DocuSigned by:
Patrick Vance

Title: Lead Maintenance

Print Name:

BC352E9D2EDD484...
Patrick Vance

Date: 7/19/2017 | 10:05 AM PDT

VEOLIA INFORMATION – DO NOT WRITE IN THIS BOX

Date Received:

7/20/2017 | 9:13 AM EDT

Checked in by:

DocuSigned by:
Sara Herzfeldt

21F8044227974B4...