

FEDERAL NOTIFICATION LETTER

Tuesday, January 30, 2018

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

CEI Electrical Service
21424 N. 20th Ave.
Phoenix, AZ 85027

To Specific Licensee:

SRB Technologies, Inc.
2580 Landmark Drive
Winston-Salem, NC 27103
(336)-659-2610
Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee)	2-27-2018
--	-----------

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name:	Barbara Lunsford
Signature:	<i>Barbara Lunsford</i>
Phone Number:	602-272-6161

FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT

VEOLIA USE ONLY

SALES ORDER: 1985409**CASE:** 35586

VEOLIA USE ONLY

RGA #: 996948**RGA # Expiration Date:** 4/29/18**UCN:** 6C51385D-8E54255F**FedEx Tracking #:** 691191700045210**Box # of #:** 1 of 1**TRITIUM EXIT SIGN INVENTORY FORM**

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1. ISOLITE	2000	A47769	7-94	11.5
2. ISOLITE	2000	A47796	7-94	11.5
3. ISOLITE	2000	A47774	7-94	11.5
4. ISOLITE	2000	A47767	7-94	11.5
5. ISOLITE	2000	A47771	7-94	11.5
6. ISOLITE	2000	A47772	7-94	11.5
7. ISOLITE	2000	A47768	7-94	11.5
8. ISOLITE	2040	A47773	7-94	11.5
9.				
10.				

Describe any damaged units:
Please email pictures of damaged signs to
pak.ts@veolia.com

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

GENERATOR CERTIFICATION

Generator Signature:

DocuSigned by:
Barbara Lunsford

Title: Vice President

Print Name:

D25CB58F95D441
Barbara Lunsford

Date: 1/23/2018 | 12:48 PM EST

VEOLIA INFORMATION – DO NOT WRITE IN THIS BOX

Date Received:

1/24/2018 | 9:09 AM EST

Checked in by:

DocuSigned by:
Angela Burns

34E89CE0E7D7428...