

# FEDERAL NOTIFICATION LETTER

Monday, March 05, 2018

Director of FSME  
Attn: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

**From General Licensee:**

Procter & Gamble  
501 Eastman Ave.  
Green Bay, WI 54302

**To Specific Licensee:**

SRB Technologies, Inc.  
2580 Landmark Drive  
Winston-Salem, NC 27103  
(336)-659-2610  
Radioactive Materials License #034-0534-2


<b>Date of Transfer:</b> (Enter Date Disposal Box was shipped to Specific Licensee)	3/16/18
--	---------

**Description of Device(s) Transferred:**

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

<b>Printed Name:</b>	Wendy Darm
<b>Signature:</b>	
<b>Phone Number:</b>	920-430-2287

**FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT**

VEOLIA USE ONLY

**SALES ORDER:** 1993638

**CASE:** 36025

VEOLIA USE ONLY

RGA #: 997025  
 RGA # Expiration Date: 5-23-18  
 UCN: 1A51389B-6C54315D  
 FedEx Tracking #: 691191700045425  
 Box # of #: 1 of 1

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1. SLC	unknown	unknown	4/1985	15
2. SLC	unknown	unknown	10/1996	15
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Describe any damaged units:  
 Please email pictures of damaged signs to  
 pak.ts@veolia.com

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

### GENERATOR CERTIFICATION

Generator Signature: Wendy Darm Title: Site Environmental Leader  
 Print Name: Wendy Darm Date: 2/22/2018 | 8:21 AM EST

### VEOLIA INFORMATION – DO NOT WRITE IN THIS BOX

Date Received: 2/22/2018 | 9:56 AM EST Checked in by: Angela Burns

