

**APPENDIX P-6
FSS FIELD LOG**

Survey Area: LSA 03 **Description:** Plant Soils Open Land Area (West)

Survey Unit: 01 **Description:** West Open Land Area ("Area 5")

Date/Time: **Observation or Comment:** **Technician**

09/30/15 Prior to commencing a GWS in LSA 03-01 a task-specific safety brief was performed by the FSS Supervisor. Before commencing the GWS the FSS personnel performed a quality walk-down. Background levels were measured at 8.5K - 9.5K gcpm. Weather conditions were partly cloudy and cool at 69 °F. Commenced a GWS of LSA 03-01 at 1521 and secured at 1629. FSS personnel returned to the office to process data and perform instrument post-checks. Jahmai Williams
Jahmai Williams

GWS files generated:
LSA_03_01_093015_D_JW

10/05/15 Prior to resuming a GWS of LSA 03-01 a task-specific safety brief was performed by the FSS Supervisor. Before commencing the GWS the FSS personnel performed a quality walk-down. Background levels were measured at 9K - 10K gcpm. Weather conditions were partly cloudy and cool dry at 69 °F. At 0921 the GWS was initiated and secured at 1128 for end of morning shift. The GWS was recommenced at 1358 and secured at 1605. FSS personnel returned to the office to process data and perform instrument post-checks. Jahmai Williams
Jahmai Williams

GWS files generated:
LSA_03_01_100515_D2_JW
LSA_03_01_100515_D2_JW
LSA_03_01_100515_Q_CC
LSA_03_01_100515_Q3_CC
LSA_03_01_100515_P_MS

10/06/15 Prior to continuing a GWS in LSA 03-01 a task-specific safety brief was performed by the FSS Supervisor. Before commencing the GWS the FSS personnel performed a quality walk-down. Background levels were measured at 8.5K - 9.5K gross cpm. Weather conditions were partly cloudy and warm at 75 °F. Commenced a GWS of LSA 03-01 at 0921 and secured at 1046. FSS personnel returned to the office to process data and perform instrument post-checks. Jahmai Williams
Jahmai Williams

GWS files generated:
LSA_03_01_100615_D_JW

Hematite
Decommissioning
Project

Procedure: HDP-PR-FSS-701, Final Status Survey Plan Development

Westinghouse Non-Proprietary Class 3

Revision: 4

Appendix P-6, Page 2 of 2

**APPENDIX P-6
FSS FIELD LOG**

Survey Area: LSA 03 **Description:** Plant Soils Open Land Area (West)

Survey Unit: 01 **Description:** West Open Land Area ("Area 5")

Date/Time: **Observation or Comment:** **Technician**

10/08/15 Prior to commencing the systematic sampling of LSA 03-01 a task-specific safety brief was performed by the FSS Supervisor. The FSS personnel performed a quality walk-down. Weather conditions were cloudy and warm at 82°F. Commenced the systematic sampling of 03-01 at 0925 and secured at 1115 for end of morning shift. Sampling was resumed at 1340 and completed at 1615. FSS personnel exited LSA 03-01 to prepare the samples for shipment. Jahmai Williams
Jahmai Williams

10/09/15 Prior to commencing the biased sampling of LSA 03-01 a task-specific safety brief was performed by the FSS Supervisor. The FSS personnel performed a quality walk-down. Weather conditions were cloudy and cool at 68°F. The bias sample was collected at 1110. FSS personnel exited LSA 03-01 to prepare the sample for shipment. Jahmai Williams
Jahmai Williams

Sample ID:
L03-01-25-P-S-B-00