

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Sterling Diagnostic, Inc. 36645 Metro Court Sterling Heights, MI 48310 REPORT NUMBER(S) 2018001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-31055	4. LICENSE NUMBER(S) 21-26030-01	5. DATE(S) OF INSPECTION December 17, 2018
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01-03.07
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03244	2. PRIORITY 5	3. LICENSEE CONTACT Noli Cruz, RSO	4. TELEPHONE NUMBER (586) 979-2141
---------------------------------	----------------------	---	---

Main Office Inspection Next Inspection Date: December 17, 2023

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was an unannounced, routine inspection of a small private company authorized to receive, store, and distribute diagnostic in-vitro kits containing iodine-125. These kits were distributed to its customers (general licensees) on an as needed basis. Approximately 140 kits were distributed annually.

PERFORMANCE OBSERVATIONS

This inspection consisted of interviews with licensee personnel, a review of select records, a tour of the kit storage area, and independent measurements. The inspector performed a confirmatory inventory of kits in the licensee's warehouse and compared the total activity with the licensee's possession limit listed on the NRC license.

No violations of NRC requirements were identified as a result of this inspection.