

**CAMECO RESOURCES
CROW BUTTE OPERATION**



**86 Crow Butte Road
P.O. Box 169
Crawford, Nebraska 69339-0169**

**(308) 665-2215
(308) 665-2341 – FAX**

January 22, 2019

**USPS PRIORITY MAIL
SIGNATURE CONFIRMATION**

Marty Link, Water Quality Division Administrator
Nebraska Department of Environmental Quality
P.O. Box 98922
Lincoln, NE 68509-8922

Class III UIC Permit NE0122611
December 2018 Monthly Restoration Report

Dear Ms. Link:

Please find enclosed the December 2018 Monthly Restoration Reports for Mine Units 2, 3, 4, 5, 6 and 7. The reverse osmosis (RO) units continue to inject permeate and reductant into Mine Unit 6 as well as Mine Unit 7. Guideline 8 samples were collected from baseline restoration wells in Mine Units 3, 4, and 5 to continue with stability monitoring in those Mine Units.

Mine Unit 2 remained in stability monitoring.

If you have any questions regarding this submittal, please feel free to contact me at (308) 665-2215, ext. 117.

Sincerely,
Cameco Resources
Crow Butte Operation

Walter D. Nelson
SHEQ Coordinator

Enclosures: As Stated

cc: Ron Burrows – NRC
CBO - File
cc: CR – Electronic File
Kory Winters – NDEQ Field Office
Amanda Jones – NDEQ Program Coordinator

CROW BUTTE MINE

MONTHLY RESTORATION REPORT

December 2018

MINE UNIT 2

1. RESTORATION ACTIVITY DURING MONTH:

	YES	NO	
a. Groundwater Transfer		X	(if yes, complete part 2)
b. Groundwater Sweep		X	(if yes, complete part 3)
c. Groundwater Treatment		X	
d. Wellfield Recirculation		X	
e. Other (explain):	X		The Mine Unit is in Stability Monitoring.

2. LIST WELLS USED IN GROUNDWATER TRANSFER DURING THE MONTH:

3. LIST WELLS USED IN GROUNDWATER SWEEP DURING THE MONTH:

4. LIST WELLS SAMPLED DURING MONTH AND ASSAY RESULTS:

No wells were sampled during the month.

CROW BUTTE MINE
MONTHLY RESTORATION REPORT

December 2018

MINE UNIT 3

1. RESTORATION ACTIVITY DURING MONTH:

	YES	NO	
a. Groundwater Transfer		X	(if yes, complete part 2)
b. Groundwater Sweep		X	(if yes, complete part 3)
c. Groundwater Treatment		X	
d. Wellfield Recirculation		X	
e. Other (explain):	X		G-8 samples collected from baseline restoration wells in December.

2. LIST WELLS USED IN GROUNDWATER TRANSFER DURING THE MONTH:

3. LIST WELLS USED IN GROUNDWATER SWEEP DURING THE MONTH:

4. LIST WELLS SAMPLED DURING MONTH AND ASSAY RESULTS:

No in-house samples were collected during the month.

CROW BUTTE MINE
MONTHLY RESTORATION REPORT

December 2018

MINE UNIT 4

1. RESTORATION ACTIVITY DURING MONTH:

	YES	NO	
a. Groundwater Transfer		X	(if yes, complete part 2)
b. Groundwater Sweep		X	(if yes, complete part 3)
c. Groundwater Treatment		X	
d. Wellfield Recirculation		X	
e. Other (explain):	X		G-8 samples collected from baseline restoration wells in December.

2. LIST WELLS USED IN GROUNDWATER TRANSFER DURING THE MONTH:

3. LIST WELLS USED IN GROUNDWATER SWEEP DURING THE MONTH:

4. LIST WELLS SAMPLED DURING MONTH AND ASSAY RESULTS:

No in-house samples were collected during the month.

CROW BUTTE MINE
MONTHLY RESTORATION REPORT

December 2018

MINE UNIT 5

1. RESTORATION ACTIVITY DURING MONTH:

	YES	NO	
a. Groundwater Transfer		X	(if yes, complete part 2)
b. Groundwater Sweep	X		(if yes, complete part 3)
c. Groundwater Treatment		X	
d. Wellfield Recirculation		X	
e. Other (explain):	X		G-8 samples collected from baseline restoration wells in December.

2. LIST WELLS USED IN GROUNDWATER TRANSFER DURING THE MONTH:

3. LIST WELLS USED IN GROUNDWATER SWEEP DURING THE MONTH:

P1002

4. LIST WELLS SAMPLED DURING MONTH AND ASSAY RESULTS:

No in-house samples were collected during the month.

CROW BUTTE MINE

MONTHLY RESTORATION REPORT

December 2018

MINE UNIT 6

1. RESTORATION ACTIVITY DURING MONTH:

	YES	NO	
a. Groundwater Transfer		X	(if yes, complete part 2)
b. Groundwater Sweep	X		(if yes, complete part 3)
c. Groundwater Treatment	X		IX and RO P1265, I1267P, I1272P, I1285P, P1314, P1315, P1337, I1356P, P1377, P1402, P1428, P1494, P1612, P1625, P1628, P1676, P1690, P1706, P1800.
d. Wellfield Recirculation		X	
e. Other (explain):		X	

2. LIST WELLS USED IN GROUNDWATER TRANSFER DURING THE MONTH:

3. LIST WELLS USED IN GROUNDWATER SWEEP DURING THE MONTH:

P1273, P1461, P1569.

4. LIST WELLS SAMPLED DURING MONTH AND ASSAY RESULTS:

No in-house samples were collected during the month.

CROW BUTTE MINE
MONTHLY RESTORATION REPORT

December 2018

MINE UNIT 7

1. RESTORATION ACTIVITY DURING MONTH:

	YES	NO	
a. Groundwater Transfer		X	(if yes, complete part 2)
b. Groundwater Sweep		X	(if yes, complete part 3)
c. Groundwater Treatment	X		IX and RO BL-17, P1957, P1972, P1986, P2014, P2035, P2038, P2040, P2108, P2188, P2219, P2241, P2264, P2303, P2316, P2340, P2359, P2361, P2384, P2395, P2399, P2401, I2429P, P2476, P2510, P2523, P2588, P2601, P2610, P2612, P2614, P2642, P2660.
d. Wellfield Recirculation		X	
e. Other (explain):		X	

2. LIST WELLS USED IN GROUNDWATER TRANSFER DURING THE MONTH:

3. LIST WELLS USED IN GROUNDWATER SWEEP DURING THE MONTH:

4. LIST WELLS SAMPLED DURING MONTH AND ASSAY RESULTS:

No in-house samples were collected during the month.