



**Docket File Information**  
**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  Digirad Imaging Solution, Inc. 1048 Industrial Ct. Ste. E Suwanee, GA 30024  REPORT NUMBER(S) 2019001	2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S)  030-38357	4. LICENSE NUMBER(S)  10-29283-02	5. DATE(S) OF INSPECTION  May 23, 2019
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED  87130	7. INSPECTION FOCUS AREAS  03.01-03.08
--	--

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)  02200	2. PRIORITY  3	3. LICENSEE CONTACT  Richard Lawhorn	4. TELEPHONE NUMBER  (812) 374-7104
---------------------------------	----------------------	--	---

Main Office Inspection                      Next Inspection Date: \_\_\_\_\_

Field Office Inspection    10752 Trenton Ave., St Louis MO \_\_\_\_\_

Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

This was an announced, routine inspection of a mobile nuclear medicine service company authorized to receive, administer, and dispatch licensed material permitted by 10 CFR 35.100 and 35.200 from six base hot lab locations. This inspection consisted of the hot lab located in St Louis, Missouri. The licensee used this location as a hub to store the vehicle with the nuclear medicine camera, survey meters, decay-in-storage waste, and related equipment. The licensee received unit doses at this location from a near by pharmacy. The licensee staffed the vehicle with a Nuclear Medicine Technician (NMT) and a nurse.

**PERFORMANCE OBSERVATIONS**

The inspector toured the facility to evaluate the licensee's measures for materials security, hazard communication, and exposure control. The inspector performed independent surveys of the van and hot lab location and found no contamination or exposures to members of the public distinguishable from background. The physicist and NMT demonstrated adequate knowledge of radiation safety principles and practices through interviews. The inspector reviewed survey meter calibrations, shipping papers, package receipt records, package contamination wipes, and waste disposal. The inspector observed the NMT and nurse wearing the appropriate dosimetry.

No violations of NRC requirements were identified as a result of this inspection.