NOTES: Column 17/18 Lateral Trench soil samples are collected from soils exposed in a channel in the floor except for the 0' sample collected from debris resting on the floor of the trench.
North Trench and South Trench soil samples are collected from drainage holes in the floor. Samples from Columns 43 to 45 are sludge from drainage holes. Three additional samples were collected of debris from the floor of the North Trench between Columns 16 and 18 and are not shown below (results of these three samples were 34, 66, and 46 pCi/g, respectively from West to East).

LEGEND:
80' = 80 feet north of South Trench
7 = Column Number
54 = 54 picocuries per gram (pCi/g) total uranium
RED = greater than 30 pCi/g total uranium
RED = greater than 436 pCi/g total uranium
(1) = Sample point determined not to be representative and not used to estimate distributed total uranium concentrations in soil (e.g., collected from shallow soil within a drainage hole rather than sampled from greater depth within drainage hole, represents soil from within a preferential pathway for contamination, rather than being representative of distributed contamination in soil underneath floor slab).