LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N Y J A F 1 2 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 4 5 6 TO CAT 58
CON'T 0 1 REPORT L 6 0 5 0 0 0 3 3 3 7 0 9 0 2 7 9 8 0 9 2 6 7 9 9
0]3
05
06
07
7 8 9
SYSTEM CODE CODE SUBCODE SUBCO
TO REPORT NUMBER 21 21 22 PREPORT NO. 0 5 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT SUBMITTED FORM SUB. TY 23 Y 24 A 25 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIED AND SUPPLIED
Please See Attachment
112 L
7 8 9
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 THE STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 THE STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 ACTIVITY CONTENT 12 3 44 45 46 80
RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA PERSONNEL EXPOSULES 44 45
7 8 9 PERSONNEL INJURIES DESCRIPTION (39) NA NA NA 80
1 3 0 0 0 0 0 0 0 NA NA NA NA
TYPE DESCRIPTION NA 1065 308
PUBLICITY ISSUED DESCRIPTION 45 NA 7910010 353 VRC USE ONLY
NAME OF PREPARER W. Verne Childs PHONE 90 80 80 80 80 80 80 80 80 80 80 80 80 80

POWER AUTHORITY OF THE STATE OF NEW YORK JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

Page 1 of 1

While shutdown in a cold condition, during the conduct of Operations Surveillance Test F-ST-12D titled "Radwaste Building Exhaust Monitor Instrument Functional Test" to satisfy the requirements of Technical Specification Appendix A, Paragraph 3.2.D.3, the "A" Radwaste Building Exhaust Monitor (17-RIS-458A) was found out of calibration. The redundant instrument (17-RIS 458B) was verified operable, therefore the event did not represent any significant hazard to the public health and safety.

The instrument was repaired, recalibrated and satisfactory operation was demonstrated by the successful completion of F-ST-12D on the following day.