NRC FORM 591M PART 1 (4-2008)			U.S. NUCLEAR REGULATORY COMMISSION		
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
LICENSEE/LOCATION INSPECTED: Grace Pacific, LLC Allied Quarry Road Kailua-Kona, Hawaii (Big Island)			NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd Arlington, Texas 76011-4511		
REPORT NO.: 2019-001 3. DOCKET NUMBER 4. LICENSE NUMBER				E DATE(C)	OF INCRECTION
030-20138		53-21273-01		5. DATE(S)	OF INSPECTION July 29, 2019
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:					
cited. This form is	s a NOTICE OF VIC	OLATION, which may be	subject to posting in ac	cordance with 10 C	FR 19.11.
Licensee's Statement of Corrective Actions for Item 4, above.					
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Signature Date					
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	James L. Th	ompson	Janus []	Dr	8/8/2019
BRANCH CHIEF	atricia	1. Silva	AR	4-1	8/23/19
NRC FORM 591M PART 1				5	
Non-Public	Sensitive - Sec	curity-Related	[X Public	X Non-Sensitive

Thompson, James

From:

Thompson, James

Sent:

Thursday, August 08, 2019 2:58 PM

To:

FSouza@gracepacific.com

Subject:

NRC Inspection Report

Attachments:

SKM_C45819080814560.pdf

Importance:

High

Ms. Souza,

Please find enclosed the NRC inspection report for the inspection performed on 7/29/2019 at your facility on the Big Island, as discussed today during the exit meeting. Please print this report out and maintain it with your records.

Mahalo,

-James