



MATERIAL TRANSMITTED HERewith
CONTAINS SENSITIVE INFORMATION
UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

MAR 31 1980

Report Nos. 50-269/80-8, 50-270/80-6, and 50-287/80-6

Docket Nos. 50-269, 50-270 and 50-287 License Nos. DPR-38, DPR-47 and DPR-55

Licensee: Duke Power Company
422 South Church Street
Charlotte, North Carolina 20247

Facility Name: Oconee 1, 2 and 3

Inspection at: Oconee site near Seneca, South Carolina

Inspection conducted: February 25-29, 1980

Date of Last Physical Security Inspection Visit: September 5-7, 1979

Type of Inspection: Unannounced Physical Security

Inspectors: J. C. Howell 3-25-80
Date

A. Tillman 3-25-80
Date

Approved by: W. J. Tobin 3-25-80
Date
W. J. Tobin, Acting Chief, Safeguards Branch

Inspection Summary

Areas Inspected: Included review of the licensee's security plan, security program audit, security organization, vital and protected area physical barriers, lighting, access controls, alarm station, detection and assessment aids, communications, testing and maintenance, compensatory measures, response, keys/locks, and records/reports.

The inspection involved 80 inspector hours on site by two NRC inspectors. The inspection was begun during an offshift period; 20 inspection hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements within the areas examined during the inspection. The corrective action for a previously identified item of noncompliance (79-24-01) pertaining to a vital area physical barrier was not completed and remains open.

S-72 80 - 36P
Copy _____ of _____ Copies
7 Pages
This Document is not to be reproduced without specific approval of IE:II