



LONG ISLAND LIGHTING COMPANY

175 EAST OLD COUNTRY ROAD • HICKSVILLE, NEW YORK 11801

Direct Dial Number

March 19, 1980

JNRC-248

Mr. Boyce Grier, Director  
Office of Inspection & Enforcement, Region 1  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Jamesport Nuclear Power Station - Units 1 & 2  
Inspection & Enforcement Bulletin No. 80-03  
Docket Nos. 50-516  
50-517

Dear Mr. Grier:

This letter is in response to Inspection & Enforcement Bulletin No. 80-03, "Loss of Charcoal from Standard Type II, 2 Inch, Tray Adsorber Cells".

We have reviewed the status of the Jamesport Nuclear Power Station and found that charcoal adsorber cells have not been purchased to date. We will ensure that this concern raised in this bulletin is adequately addressed by the vendor prior to award of the purchase order.

Should you require further information, please do not hesitate to contact us.

Very truly yours,

R. E. Plaskon  
Assistant Project Manager  
Jamesport Nuclear Power Station

LG/dm

cc: Mr. J. H. Sniesek, Director  
Division of Fuel Facilities and  
Materials Safety Inspection  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8004220036