

Metropolitan Edison Company Post Office Box 480 Middletown, Pennsylvania 17057 717 944 4041

Wester's Direct Diel Number

## POOR ORIGINAL February 19, 1980

Office of Inspection and Enforcement Attn: Boyce H. Grier. Director Region I U. S. Muclear Regulatory Commission 631 Fark Avenue King of Prussia, Pa. 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit II (TMT-2)
Operating License No. DPR-73
Docket No. 50-320
Reportable Occurrence No. 80-05/19

This Lelegram Ls to confirm the telecon between Mr. G. A. Kunder, Unit IT Supervisor Technical Specification Compliance, and Mr. Rich Conti, Region I, NRC at 1530 hours on February 19, 1980.

A situation considered reportable under Technical Specification 6.9.1.8.b was entered at 1700 on February 18, 1980 wherein Technical Specification 3.8.1.1.b was violated.

The B diesel generator had been out of service for an annual maintenance inspection as permitted by the previous TM1 il l'echnical Specifications in effect prior to 1700 February 15, 1980. At this time, the new Unit II Recovery Technical Specification order went into effect. The new Tech Specs required both diesels to be operable and since the B diesel generator was unable to be placed back into service within the 72 hour time period required by the new action statement, a noncompliance resulted.

Purther details and followup action will be discussed in the followup report.

Sincerely,

G. A. Kunder

Supervisor Technical Specification Compliance

CAK: SDC:hah

cc: J. T. Collins

405/10

Metropolitan Edison Conquiny is a Mumber of the General Public Utilities System

665