


Department of Energy

Albuquerque Operations Office P.O. Box 5400 Albuquerque, New Mexico 87115 RETURN ORIGINAL TO POR, HQ.

OCT 2 0 1989

Mr. James G. Oldham Project Director MK-Ferguson Company P.O. Box 9136 Albuquerque, NM 87119

Dear Jim,



Enclosed are two (2) copies of the Quality Assurance (QA) Report Number S130, Surveillance of the MK-Ferguson Company, which provides the results of the September 13, 1989 QA Surveillance at Tuba City, Arizona. Also enclosed is the Report on Tuba City Disposal Cell Observations of Cover Cracking. The reports conclude the Tuba City construction activities are being performed in general compliance with the Remedial Action Inspection Plan and specification requirements. The surveillance resulted in six (6) observations with one recommendation being issued. No response is required.

Should you have any questions or comments concerning this matter, please contact Milt Scoutaris of my staff at 845-1200.

Sincerely,

Mark L. Matthews

Acting Project Manager

Uranium Mill Tailings Project Office

2 Enclosures

cc w/enclosures:

E. Hawkins, NRC

L. Shingoitewa, Hopi Nation

M. Begaye, Navajo Nation

M. Abrams, UMIRA

M. Scoutaris, UMTRA

cc w/n enclosures:

K. Agogino, JEG B. Bearden, JEG 8912060090 891020 PDR WASTE

DESIGNATED ORIGINAL

Control By Many c. Hard

90-0068