



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

~~RE: [unclear]~~ FF4m

February 3, 1981

Mr. James G. Keppler, Director
Directorate of Inspection and
Enforcement - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Eilyn, IL 60137

Subject: Dresden Station Units 1, 2, and 3
Additional Response to IE Inspection
Report Nos. 50-10/80-21, 50-237/80-23,
and 50-249/80-27
NRC Docket Nos. 50-10/237/249

Reference (a): J. Abel letter to J. Keppler dated December 18,
1980

Dear Mr. Keppler:

Reference (a) provided Dresden Station's response to to an item of noncompliance identified in the subject IE Inspection Report. Subsequently, Mr. M. Phillips of your office requested additional informaton concerning our response.

The item of noncompliance identified a failure to collect and conduct the analyses required by our Technical Specifications of cooling water samples during the week of August 11-17, 1979. Our response indicated that we were preparing a letter to Eberline Instrument Corporation to reinforce to their management the necessity of strict compliance with sample collection and analyses frequency as set forth in the radiological environmental monitoring program. After further discussions, we have also decided to establish a log which will be filled out by the Eberline representative when he collects the samples from our station. Our management personnel will periodically review this log to ensure that the required samples were indeed picked up at the station as required. We feel these actions will provide the necessary controls to ensure compliance with our Technical Specifications is maintained.

Very truly yours,

Robert J. S. Abel
for J. S. Abel
Director of
Nuclear Licensing

cc: RIII Inspector - Dresden
03208

FEB 05 1981

8108060 465