U. S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

REGION I

| Decemb No. | 50-244/81-05 | |
|--|--|------------------------------|
| Report No. | | |
| Docket No. | 50-244 License No. DPR-18 | Safeguards GroupIV |
| Licensee: | Rochester Gas an Electric Corporation | |
| | 89 East Avenue | |
| | Rochester, New York 14649 | |
| Facility Na | ame: R. E. Ginna Nuclear Power Plant | |
| Inspection | At: Ontario, New York | |
| Inspection | Conducted: February 9-13, 1981 | |
| Date of Las | st Physical Security Inspection July | y 6-11, 1980 |
| Type of Ins | spection: Routine, Unannounced, Physical Pro | otection |
| | | 3/4/8/ |
| , | J-R. H. A. Adun, Physical Security Inspector | date |
| | | |
| | | date |
| | | date , |
| (| | 2/2/8/ |
| Approved by | James W. Devlin, Chief, Physical Protection | o date |
| Inspection | Section, Technical Inspection Granch | |
| AND DESCRIPTION OF THE PROPERTY OF THE PROPERT | on February 9-13, 1981 (Report No. 50-244/81- | -05) |
| Areas Inspe | cted: Security Plan; Security Program Audit: | : Security Organization: |
| Access Cont | rriers (Protected Area); Physical Barriers (Vocal (Identification, Authorization and Badgin | /ital Area); Lighting; |
| (Search); A | ccess Control (Escorting); Access Control (V | ital Areas); Alarm Stations; |
| Detection A | ids; Assessment Aids; Communications; Testing ures; Power Supply; Response; Locks, Keys and | g and maintenance; Compen- |
| Records and | Reports. Follow-up on a previously identify | ed item of noncompliance. |
| The inspect | ion involved thirty (30) inspector-hours onsi | ite by one NRC Regional |
| (3) inspect | ctor. The inspection was initiated during no ion hours were conducted during off shift per | riods. |
| Results: T | he licensee was found to be in compliance wit (20) areas examined. | th NRC requirements in |