

The Light company

Houston Lighting & Power

P.O. Box 1700 Houston, Texas 77001 (713) 228-9211


January 16, 1990
ST-HL-AE-3339
File No.: T07.03
10CFR50

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project Electric Generating Station
Unit 1
Docket No. STN 50-498
Unit 1 First Refueling Outage Inservice
Summary Report for Repairs and Replacements

Enclosed is the Unit 1 first refueling outage (1RE01) Inservice Inspection Summary Report for Repairs and Replacements performed under the ASME Code, Section XI at the South Texas Project Electric Generating Station. This Summary Report includes the period from commercial operation (August 25, 1988) to completion of the first refueling outage (October 19, 1989).

If you should have any questions on this matter, please contact Mr. A. W. Harrison at (512) 972-7298 or myself at (512) 972-8530.


M. A. McBurnett
Manager
Support Licensing

MAM/SDP/nl

Attachments: Per Attached Index

9001300125 900116
FDR ADOCK 05000498
Q PDC

A1/021.N11

A Subsidiary of Houston Industries Incorporated

9001220201
3
A047
11

Houston Lighting & Power Company
South Texas Project Electric Generating Station

ST-HL-AE- 3339
File No.: T07.03
Page 2

cc:

Regional Administrator, Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

George Dick, Project Manager
U.S. Nuclear Regulatory Commission
Washington, DC 20555

J. I. Tapia
Senior Resident Inspector
c/o U. S. Nuclear Regulatory
Commission
P. O. Box 910
Bay City, TX 77414

J. R. Newman, Esquire
Newman & Holtzinger, P.C.
1615 L Street, N.W.
Washington, DC 20036

D. E. Ward/R. P. Verret
Central Power & Light Company
P. O. Box 2121
Corpus Christi, TX 78403

J. C. Lanier
Director of Generation
City of Austin Electric Utility
721 Barton Springs Road
Austin, TX 78704

R. J. Costello/M. T. Hardt
City Public Service Board
P. O. Box 1771
San Antonio, TX 78296

Rufus S. Scott
Associate General Counsel
Houston Lighting & Power Company
P. O. Box 61867
Houston, TX 77208

INPO
Records Center
1100 Circle 75 Parkway
Atlanta, GA 30339-3064

Dr. Joseph M. Hendrie
50 Bellport Lane
Bellport, NY 11713

D. K. Lacker
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78704

Revised 12/15/89

L4/NRC/

INDEX OF ATTACHMENTS

1. Cover Sheet
2. 1RE01 Inservice Inspection Summary Report for Repairs and Replacements.