U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-331/82-20(DETP)

Docket No. 50-331

License No. DPR-49

Safeguards Group IV

Licensee: Iowa Electric Light and Power Company Post Office Box 351

Cedar Rapids, IA 52406

Facility Name: Duane Arnold Energy Center

Inspection At: Duane Arnold Energy Center, Palo, IA

Inspection Conducted: December 6-10, 1982

Date of Last Physical Security Inspection: June 21-25, 1982

Type of Inspection: Routine, Unannounced, Physical Protection

Physical Protection Specialist

Physical Protection Specialist

Approved By:

eguards Section

Inspection Summary

Inspection on December 6-10, 1982 (Report No. 50-331/82-20(DETP)) Areas Inspected: Included a review of Security Organization - Management; Security Organization - Personnel; Records and Reports; Testing and Maintenance; Physical Barriers - Protected Area; Physical Barriers - Vital Areas; Access Control - Personnel; Access Control - Packages; Access Control -Vehicles; Detection Aids - Protected Area; Detection Aids - Vital Areas; Independent Inspection Effort; and Followup on Previous Items. The inspection involved 72 inspector-hours onsite by two NRC inspectors. The inspection began during the day shift; six inspection hours were accomplished during the off-shift periods.

Results: The licensee was found to be in compliance with NRC requirements within the areas examined. All previously identified items of noncompliance were found to have been satisfactorily corrected and action taken to prevent

recurrence. One previously identified item of concern remains open.

(Details - UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure Contains SAFEGUARDS INFORMATION Upon Separation This Page is Decontrolled