

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION P. O. BOX 128 SAN CLEMENTE, CALIFORNIA 92674-0128

R. W. KRIEGER

Subject:

2 2

TELEPHONE (714) 366-6255

A047

. .

October 19, 1990

U. S. Nuclear Regulatory Commission Document Control Desk Washington, L.C. 20555

> Docket No. 50-362 Owner's Report of Inservice Inspection, Form NIS-1 San Onofre Nuclear Generating Station, Unit 3

Reference: American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code, Section XI, 1977 Edition with Addenda through Summer 1979

The purpose of this letter is to submit a copy of the Inservice Inspection Summary Report, including the Owner's Report of Repairs and Replacements for the San Onofre Nuclear Generating Station, Unit 3. This report is submitted to meet the requirements of Paragraph IWA-6230 of the above reference, and covers the inservice examinations of Class 1 and Class 2 pressure retaining components and their supports.

This report covers the period from August 21, 1988, through July 23, 1990, the date of the unit's return to service following the Cycle V Refueling Outage. If you require any further information, please so advise.

incerely.

Enclosures

cc:

9010230097

DR

ADOCK

05000362

C. W. Caldwell (USNRC Senior Resident Inspector, Units 1, 2 and 3) J. B. Martin (Regional Administrator, USNRC Region V), w/enclosures

