



**Commonwealth Edison**

Zion Generating Station  
101 Shiloh Blvd.  
Zion, Illinois 60099  
Telephone 708 / 746-2084

December 14, 1993  
ZRAD-93-036

U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Attn: Document Control Desk

Subject: Zion Nuclear Power Station Units 1 and 2  
Zion Station Steam Generator Inspection Activities  
NRC Docket Numbers 50-295 and 50-304

Reference: Zion Station Technical Specifications Section 4.3.1.B.5

In accordance with Technical Specification 4.3.1.B.5.A, Zion Station is reporting the following number of tubes plugged or repaired (by sleeving) in each of the Unit One Steam Generators as a result of the most recent inspection:

Steam Generator	Tech. Spec. Repairs	Preventive Repairs	Total Repairs
(A) IRC100	0	15	15
(B) IRC400	1	40	41
(C) IRC200	0	33	33
(D) IRC300	0	13	13

If there are any questions or comments regarding this report, please refer them to Mr. Tom Cook of the Zion Station Support Engineering Department at (708) 746-2084 ext. 3172.

Sincerely,

M. E. Lohmann  
Site Engineering & Construction Mgr.  
Zion Station

MEL/TMC/sks

cc: NRC Region III Administrator  
NRC Senior Resident Inspector  
INPO Record Center  
IDNS Chief of Code Compliance  
CECo Distribution List

9312210062 931214  
PDR ADOCK 05000295  
PDR

ZCORRRA.NRC

A001  
111

ZRAD-93-036

CECo Distribution List

cc: D. Wozniak  
S. Kaplan  
T. Broccolo  
M. Rauckhorst  
J. Reiss  
A. Panagos  
J. Blomgren  
T. M. Cook  
R. Tanninga  
Master File  
Reg Assurance File