DCDDCB

IE07

MAR 0 1 1994

B. P. Oil Company ATTN: Dennis Jonke, Manager Health, Safety and Environment 200 Public Square, 7-4655-D Cleveland, OH 44114 License No. SUB-941 (Terminated) Docket No. 040-007753 (Terminated)

Dear Mr. Jonke:

SUBJECT: REVIEW OF STANDARD OIL COMPANY FILES POSSESSED BY BP AMERICA (LICENSE NO. SUB-941)

This refers to your telephone conversation with Mr. Ken Lambert of my staff. During this call we requested information regarding the Standard Oil Company, a former NRC licensee who conducted licensed activities at your facility. However, it was indicated that before providing this information, that we provide you a letter describing our reasons for requesting this information.

The NRC recently undertook an initiative to review license file documents of formerly terminated licenses. This was to identify licenses which may have been closed-out with insufficient data to determine if residual radioactive materials remained. The license file review attempts to identify documentation regarding decontamination activities, disposal of radioactive materials, and close-out surveys. When documentation does not exist in license files, attempts are made to contact the former licensee or current owner of the property, to request any documentation that may exist. If documentation does not exist, a radiological survey of the facility is scheduled. The survey is conducted to ensure that residual radioactive material does not remain on building surfaces in excess of NRC's unrestricted use criteria.

Due to insufficient information in our files, we request that BP America review its files for any records pertaining to Standard Oil Company License No. SUB-941 and contact any long-time employees who may have knowledge of licensed activities. If records are located and pertain to close-out surveys or onsite disposal, we request copies of those records for NRC review.

If records pertaining to onsite disposal and close-out surveys cannot be located or are reviewed by NRC and deemed inadequate to determine the radiological status of the pilot plant, we wish to conduct surveys of the pilot plant, grounds outside pilot plant, all possible onsite disposal areas, and storage areas on March 8-9, 1994.

070023

9403080119 940301 PDR ADOCK 040***** C PDR

B. P. Oil Company

I you have any questions, need additional information, or if March 8-9, 1994 is an unacceptable date for the survey please contact Ken Lambert at 708/829-9853 or myself at 708/829-9856.

Sincerely,

Sune m. m. C

George M. McCann, Chief Fuel Facilities and Decommissioning Section

RIII Lambert/dp .02/ /94

RIII SWAA McCann JGJ