

The Light company

Houston Lighting & Power South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483

September 14, 1990

ST-HL-AE-3563

File No.: T07.03

10CFR50

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project Electric Generating Station
Unit 1


Docket No. STN 50-498

Unit 1 Second Refueling Outage Inservice

Summary Report for System Pressure Tests

Enclosed is the Unit 1 second refueling outage (1RE02) Inservice Inspection Summary Report for System Pressure Tests performed under the ASME Code, Section XI at the South Texas Project Electric Generating Station. This Summary Report includes the period from the first refueling outage (October 19, 1989) to the second refueling outage (June 21, 1990).

If you should have any questions on this matter, please contact Mr. A. W. Harrison at (512) 972-7298 or myself at (512) 972-8530.


M. A. McBurnett
Manager
Licensing

MAM/sDP/nl

Attachments: Per Attached Index

00000
9010010162 900914
PDR ADOCK 05000498
Q PDC

14047
1/1

Houston Lighting & Power Company
South Texas Project Electric Generating Station

ST-HL-AE-3563
File No.: T07.03
Page 2

cc:

Regional Administrator, Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

George Dick, Project Manager
U.S. Nuclear Regulatory Commission
Washington, DC 20555

J. I. Tapia
Senior Resident Inspector
c/o U. S. Nuclear Regulatory
Commission
P. O. Box 910
Bay City, TX 77414

J. R. Newman, Esquire
Newman & Holtzinger, P.C.
1615 L Street, N.W.
Washington, DC 20036

R. P. Varret/D. E. Ward
Central Power & Light Company
P. O. Box 2121
Corpus Christi, TX 78403

J. C. Lanier/M. B. Lee
Director of Generation
City of Austin Electric Utility
721 Barton Springs Road
Austin, TX 78704

R. J. Costello/M. T. Hardt
City Public Service Board
P. O. Box 1771
San Antonio, TX 78296

Rufus S. Scott
Associate General Counsel
Houston Lighting & Power Company
P. O. Box 61867
Houston, TX 77208

INPO
Records Center
1100 Circle 75 Parkway
Atlanta, GA 30339-3064

Dr. Joseph M. Hendric
50 Bellport Lane
Bellport, NY 11713

D. K. Lackner
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

Revised 08/31/90

L4/NRC/

INDEX OF ATTACHMENTS

1. Cover Sheet.
2. Scope: 1RE02 System Pressure Tests.
3. NIS-1 Owner's Report for System Pressure Tests for Class 1, 2, and 3 components of STPEGS Unit 1, including system pressure tests per IWA-5211 (a) and IWA-5214 (e).