



SAFEGUARDS INFORMATION

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION II

101 MARIETTA ST., N.W., SUITE 3100

ATLANTA, GEORGIA 30303

December 30, 1982

Report No. 50-389/82-76

Docket No. 50-389

License No. CPPR-144

Licensee: Florida Power and Light Company
9250 West Flagler Street
Miami, FL 33408

Facility Name: St. Lucie 2

Inspection at: Fort Pierce, FL

Inspection conducted: December 13-17, 1982

Date of Last Physical Security Inspection Visit: August 16-20, 1982 (Unit 1)

Type of Inspection: Unannounced Physical Security

Inspectors: William J. Tobin
D. E. Moore, Physical Security Inspector

12/30/82
Date Signed

B. L. Hall
B. L. Hall, Physical Security Inspector

12/30/82
Date Signed

Approved by: William J. Tobin
D. R. McGuire, Chief, Physical Security Section
Safeguards Branch, Division of Emergency
Preparedness and Materials Safety Programs

12/30/82
Date Signed

Inspection Summary

Areas Inspected: Included Site Orientation; Security Plan and Implementing Procedures; Security Organization-Management; Security Organization-Personnel; Security Organization-Response; Security Program Audit; Records and Reports; Testing and Maintenance; Locks, Keys, and Combinations; Physical Barriers-Protected Areas; Physical Barriers-Vital Areas; Security System Power Supply, Assessment Aids; Access Control-Personnel; Access Control-Packages; Access Control-Vehicles; Detection Aids-Protected Areas; Detection Aids-Vital Area; Alarm Stations; and Communications.

The inspection involved 60 inspector hours onsite by two NRC inspectors. The inspection was begun during a normal shift period; eight inspection hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements within the 20 areas examined during the inspection.

8301040706 821230
PDR ADDCK 05000389
Q PDR

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.

SAFEGUARDS INFORMATION