



Southern California Edison Company

23 PARKER STREET
IRVINE, CALIFORNIA 92718

March 25, 1994

WALTER C. MARSH
MANAGER OF NUCLEAR REGULATORY AFFAIRS

TELEPHONE
(714) 454-4403

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket No. 50-362
Owner's Report of Inservice Inspection, Form NIS-1
San Onofre Nuclear Generating Station, Unit 3

Reference: American Society of Mechanical Engineers (ASME) Boiler and
Pressure Vessel Code,
Section XI, 1977 Edition with Addenda through Summer 1979

The purpose of this letter is to submit a copy of the Inservice Inspection
Summary Report, including the Owner's Reports of Repairs and Replacements for
the San Onofre Nuclear Generating Station, Unit 3. This report is submitted
to meet the requirements of Paragraph IWA-6230 of the above reference, and
covers the inservice examinations of Class 1 and Class 2 pressure retaining
components and their supports.

This report covers the period from March 31, 1992, through December 30, 1993,
the date of the unit's return to service following the Cycle 7 Refueling
Outage. If you require any further information, please so advise.

Sincerely,

Enclosures

cc: K. E. Perkins, Jr., Acting Regional Administrator, USNRC Region V
M. B. Fields, NRC Project Manager, San Onofre Units 2 and 3
J. A. Sloan, Senior Resident Inspector, San Onofre Units 1, 2 and 3

310028

9403310216 940325
PDR ADOCK 05000362
G PDR

AD47 / 1