



SAFEGUARDS INFORMATION
 UNITED STATES
 NUCLEAR REGULATORY COMMISSION
 REGION II
 101 MARIETTA ST., N.W., SUITE 3100
 ATLANTA, GEORGIA 30303

JUN 29 1982

Report No. 50-335/82-23

Docket No. 50-335

License No. DPR-67

Licensee: Florida Power and Light Company
 9250 West Flagler Street
 Miami, FL 33101

Facility Name: St. Lucie 1

Inspection at: Fort Pierce, FL

Inspection conducted: June 13-17, 1982

Date of Last Physical Security Inspection Visit: February 16-19, 1982

Type of Inspection: Unannounced Physical Security

Inspector: D. E. Moore 6/29/82
 D. E. Moore, Physical Security Inspector Date Signed

Approved by: D. R. McGuire 6/29/82
 D. R. McGuire, Chief, Physical Protection Section Date Signed
 Technical Inspection Branch, Division of
 Engineering and Technical Programs

Inspection Summary

Areas Inspected: Included a Site Orientation; Review of Security Plan and Implementing Procedures; Security Program Audit; Records and Reports; Testing and Maintenance; Locks, Keys and Combinations; Physical Barriers-Protected Area; Security System Power Supply; Lighting; Access Control-Personnel, Packages and Vehicles; Detection Aids-Protected and Vital Areas; Alarm Stations; Communication; and Independent Inspection Effort.

The inspection involved 34 inspector hours on site by one NRC inspector. The inspection was begun during an offshift period; two inspection hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements within the 16 areas examined during the inspection except as follows:
 Failure to perform personnel search.

S-F2 82-110
 Copy 4 of 2 Copies
7 Pages
 This Document is not to be reproduced without specific approval of IE:II

8209140213 820910
 PDR ADDCK 05000335
 Q PDR

ENCLOSURE CONTAINS
 SAFEGUARDS INFORMATION.
 UPON SEPARATION THIS
 PAGE IS DECONTROLLED.