SAFETY INSPECTION

University of Puerto Rico Agricultural Experiment Station Mayaguez Campus Mayaguez, Puerto Rico 00708

REGIONAL OFFICE U. S. Nuclear Regulatory Commission Region II, Suite 3100 101 Marietta St. N. W. Atlanta, Georgia 30303

030-01182	4. LICENSE NUMBER(S) 52-01986-01	5. DATE OF INSPECTION 9/2/82
ensee:		
e inspection was an examination of the a	activities conducted under your license as they rela	ite to radiation safety and to compliance with the Nuclear
gulatory Commission's (NRC) rules and r	egulations and the conditions of your license. The	e inspection consisted of selective examinations of procedures
		e findings as a result of this inspection are as follows:
1. Within the scope of this inspection, t		
Commence of this mapped that	to violations were observed.	
2. The inspector also verified the steps	you have taken to correct the violations identified	during the last inspection. We have no further questions on
those actions at this time.		
	ur activities, as checked below, were in violation of	
THIS IS A NOTICE OF VIOLATIC	N which is required to be posted in accordance with	th 10 CFR 19.11
		. 10 CFR 20.203(b), (c), (d), (e) or 34.4
8. Containers located in		ware not proper
and the same of th	of radioactive material. 10 CFR 20.203(f)(1), or (f	were not proper f)(2).
C	al at the according of the	of sealed sources were not performed at the prop
frequencies. 10 CFR		License Condition Number
		were not properly maintaine
10 CFR	or License Con	ndition Number
E. Documents were not properly po	sted or otherwise made available, 10 CFR 19.11.	
	sted of otherwise made available, 10 CFR 19.11.	
F. Reports or notifications of		were not made in accordance
	or License Con	ndition Number
H		
1.		
J		

8210010114 820902 NMS LIC30 52-01986-01 PDF PDR SIGNATURE - LICENSEE

DATE

SIGNATURE - NEC INSPECTOR