



SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION II

101 MARIETTA ST., N.W., SUITE 3100

ATLANTA, GEORGIA 30303

September 13, 1982

Report No. 50-335/82-30 and 50-389/82-41

Docket No. 50-335 and 50-389

License No. DPR-67 and CPPR-144

Licensee: Florida Power and Light Company
9250 West Flagler Street
Miami, FL 33152

Facility Name: St. Lucie

Inspection at: Ft. Pierce, Florida

Inspection conducted: August 16-20, 1982

Date of Last Physical Security Inspection Visit: June 13-17, 1982

Type of Inspection: Unannounced Physical Security

Inspectors: R. Goode
R. Goode, Physical Security Inspector

8 September 1982
Date Signed

For W. Stansberry
W. Stansberry, Physical Security Inspector

9/10/82
Date Signed

Approved by: D. R. McGuire
D. R. McGuire, Chief, Physical Protection Section

9/10/82
Date Signed

Inspection Summary

Areas Inspected: Included review of Security Plan and Implementing Procedures; Security Organization; Records and Reports; Testing and Maintenance; Locks, Keys and Combinations; Physical Barriers; Security System Power Supply; Lighting, Assessment Aids; Access Control; Detection Aids; Alarm Stations and Communications.

The inspection involved 72 inspector hours by two NRC inspectors. The inspection was begun during an onshift period; 6 inspection hours were accomplished during offshift periods.

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.

SAFEGUARDS INFORMATION

8210260515 821022
PDR ADOCK 05000335
PDR

Results: The licensee was found to be in compliance with NRC requirements within the areas examined during the inspection except for the following 3 items:

1. Failure to comply with Security Plan Section 1.6.2, concerning vehicle control.
2. Failure to comply with Security Plan Section 3.1.4, concerning alarms.
3. Failure to comply with Security Plan Section 3.1.4 concerning compensatory action.

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.