

OPERATING DATA REPORT

DOCKET NO. 50-289
 DATE November 15, 1981
 COMPLETED BY C. W. Smyth
 TELEPHONE (717) 948-8551

OPERATING STATUS

1. Unit Name: Three Mile Island Nuclear Station, Unit 1
2. Reporting Period: October, 1981
3. Licensed Thermal Power (MWt): 2535
4. Nameplate Rating (Gross MWe): 871
5. Design Electrical Rating (Net MWe): 819
6. Maximum Dependable Capacity (Gross MWe): 840
7. Maximum Dependable Capacity (Net MWe): 776
8. If Changes Occur in Capacity Ratings (Items Number 3 Through 7) Since Last Report. Give Reasons:

9. Power Level To Which Restricted, If Any (Net MWe): _____
10. Reasons For Restrictions, If Any: _____

	This Month	Yr.-to-Date	Cumulative
11. Hours In Reporting Period	<u>745.</u>	<u>7296.</u>	<u>62809.</u>
12. Number Of Hours Reactor Was Critical	<u>0.0</u>	<u>0.0</u>	<u>31731.8</u>
13. Reactor Reserve Shutdown Hours	<u>0.0</u>	<u>0.0</u>	<u>839.5</u>
14. Hours Generator On-Line	<u>0.0</u>	<u>0.0</u>	<u>31180.9</u>
15. Unit Reserve Shutdown Hours	<u>0.0</u>	<u>0.0</u>	<u>0.0</u>
16. Gross Thermal Energy Generated (MWH)	<u>0.0</u>	<u>0.0</u>	<u>76531071.</u>
17. Gross Electrical Energy Generated (MWH)	<u>0.</u>	<u>0.</u>	<u>25484330.</u>
18. Net Electrical Energy Generated (MWH)	<u>0.</u>	<u>0.</u>	<u>23840053.</u>
19. Unit Service Factor	<u>0.0</u>	<u>0.0</u>	<u>49.6</u>
20. Unit Availability Factor	<u>0.0</u>	<u>0.0</u>	<u>49.6</u>
21. Unit Capacity Factor (Using MDC Net)	<u>0.0</u>	<u>0.0</u>	<u>48.3</u>
22. Unit Capacity Factor (Using DER Net)	<u>0.0</u>	<u>0.0</u>	<u>46.3</u>
23. Unit Forced Outage Rate	<u>100.0</u>	<u>100.0</u>	<u>43.8</u>

25. If Shut Down At End Of Report Period, Estimated Date of Startup: _____
26. Units In Test Status (Prior to Commercial Operation):

INITIAL CRITICALITY _____
 INITIAL ELECTRICITY _____
 COMMERCIAL OPERATION _____

	Forecast	Achieved
INITIAL CRITICALITY	_____	_____
INITIAL ELECTRICITY	_____	_____
COMMERCIAL OPERATION	_____	_____

AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 50-289
 UNIT TMI-I
 DATE November 15, 1981
 COMPLETED BY C. W. Smyth
 TELEPHONE (717) 948-8551

MONTH October, 1981

DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
1	0
2	0
3	0
4	0
5	0
6	0
7	0
8	0
9	0
10	0
11	0
12	0
13	0
14	0
15	0
16	0

DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
17	0
18	0
19	0
20	0
21	0
22	0
23	0
24	0
25	0
26	0
27	0
28	0
29	0
30	0
31	0

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH October

DOCKET NO. 50-289
 UNIT NAME TMI-1
 DATE November 15, 1981
 COMPLETED BY C. W. Smyth
 TELEPHONE (717) 948-8551

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
1	10/1/81	F	745	D	1				Regulatory Restraint Order

¹
 F: Forced
 S: Scheduled

²
 Reason:
 A-Equipment Failure (Explain)
 B-Maintenance of Test
 C-Refueling
 D-Regulatory Restriction
 E-Operator Training & License Examination
 F-Administrative
 G-Operational Error (Explain)
 H-Other (Explain)

³
 Method:
 1-Manual
 2-Manual Scram.
 3-Automatic Scram.
 4-Other (Explain)

⁴
 Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

⁵
 Exhibit I - Same Source

OPERATING SUMMARY

The unit was in cold shutdown the entire report period by order of the NRC. Core cooling was provided by the Decay Heat Removal System.

MAJOR SAFETY RELATED MAINTENANCE

Reactor Coolant Pump "C" (RC-P-1C) would not rotate by hand. The Reactor Coolant System was partially drained to permit pump to motor uncoupling. Measurements with the oil lift system in service were performed to ensure proper lift operations. These measurements were taken with satisfactory results. The pump/motor were uncoupled and attempts were made to rotate the motor. The motor would not rotate by hand. Inspections of the motor oil system and motor bearings were performed. A broken oil fitting to the #6 shoe on the upper bearing was replaced and the oil system returned to normal operation. A rotation check on the motor was performed by hand with satisfactory results. Alignment of the pump to motor is in progress.

Cavitating venturies were installed in the Emergency Feedwater System (Restart Modification LM-13). The following work was performed.

- A. The system was drained and isolated.
- B. The piping was cut and prepped for installation of venturies.
- C. Fitup/Welding.
- D. Welding inspections performed with satisfactory results.

Testing of the cavitating venturies will be performed at a later time.

REFUELING INFORMATION REQUEST

1. Name of Facility:

Three Mile Island Nuclear Station, Unit I

2. Scheduled date for next refueling shutdown:

Unknown

3. Scheduled date for restart following refueling:

Unknown

4. Will refueling or resumption of operation thereafter require a technical specification change or other license amendment?

If answer is yes, in general, what will these be?

If answer is no, has the reload fuel design and core configuration been reviewed by your Plant Safety Review Committee to determine whether any unreviewed safety questions are associated with the core reload (Ref. 10 CFR Section 50.59)?

If no such review has taken place, when is it scheduled?

Amendment No. 50, Cycle 5 reload, was approved on 3-16-79.

5. Scheduled date (s) for submitting proposed licensing action and supporting information:

N/A

6. Important licensing considerations associated with refueling, e.g. new or different fuel design or supplier, unreviewed design or performance analysis methods, significant changes in fuel design, new operating procedures:

N/A

7. The number of fuel assemblies (a) in the core, and (b) in the spent fuel storage pool:

(a) 177

(b) 208

8. The present licensed spent fuel pool storage capacity and the size of any increase in licensed storage capacity that has been requested or is planned, in number of fuel assemblies:

The present licensed capacity is 752. There are no planned increases at this time.

9. The projected date of the last refueling that can be discharged to the spent fuel pool assuming the present licensed capacity:

1986 is the last refueling discharge which allows full core off-load capacity (177 fuel assemblies).