



Department of Energy
Albuquerque Operations Office
P.O. Box 5400
Albuquerque, New Mexico 87115

JAN 31 1991

Vicinity Property No. RT-097
Address: South 4th West
Riverton, Wyoming 82501

Bad Water Lines
642 South Federal
Riverton, Wyoming 82501

Dear Sir:

Under the Uranium Mill Tailings Radiation Control Act of 1978 (Public Law 95-604), the U.S. Department of Energy (DOE), with ten percent funding provided by the state, has completed remedial action at the property listed above. Review of the available data indicates your property has been cleared of residual radioactive contamination to the extent required by the Environmental Protection Agency (EPA) Standards (40 CFR Part 192). Therefore, the DOE certifies your property is in compliance with the EPA Standards.

The current status of your property will be recorded by the state on the appropriate property records, per requirements of Public Law 95-604. Records of Uranium Mill Tailings Remedial Action vicinity Properties are archived with both the state and the DOE.

Should you have any questions regarding the project or your property, please write to me at the above address or contact Gaeton Falance of my staff at (505) 845-5636 or the Wyoming Department of Environmental Quality (307) 777-7756. Your cooperation in the successful accomplishment of this work has been greatly appreciated.

Sincerely,

Mark L Matthews

Mark L. Matthews
Project Manager
Uranium Mill Tailings Remedial
Action Project Office

9102120388 910131
PDR WASTE PDR
WM-39

cc:
Roger Shaffer, DEQ, WY

bcc:
D. Gillen, NRC
J. Oldham, MK-F
VPDMS, JEG

CONCURRENCES

RTG SYMBOL
UMTRA:JS
INITIALS/SIG *JS*
GFalance..
DATE
01/24/91

RTG SYMBOL
UMTRA
INITIALS/SIG
JS jeval
DATE
1/23/91

RTG SYMBOL
UMTRA
INITIALS/SIG
MMatthews
DATE

RTG SYMBOL
INITIALS/SIG
DATE

RTG SYMBOL
INITIALS/SIG
DATE

RTG SYMBOL
INITIALS/SIG
DATE

RTG SYMBOL
INITIALS/SIG
DATE

RTG SYMBOL
INITIALS/SIG
DATE

127035

ADD: DGillen

WM-39

NLO4

United States Government

Department of Energy


Albuquerque Operations Office

memorandum

DATE: JAN 31 1991
 REPLY TO: UMTRA:GF
 ATTN OF:
 SUBJECT: Certification of Vicinity Property No. RT-097, Located at
 South 4th West, Riverton, Wyoming,
 From the Uranium Mill Tailings Remedial Action Program
 TO: Official Location Folder

In accordance with provisions of the Uranium Mill Tailings Radiation Control Act of 1978 (PL 95-604), the subject property has been evaluated against the Environmental Protection Agency (EPA) Standards for Remedial Action at Inactive Uranium Processing sites (40 CFR Part 192) after the completion of remedial action. The Completion Report was prepared by MK-Ferguson Company, the U.S. Department of Energy (DOE) Remedial Action Contractor.

The DOE has reviewed the Completion Report and associated documentation which indicate the property has been cleared of residual radioactive contamination; therefore, the DOE certifies the property is in compliance with the EPA Standards.



Frank Bosiljevac
 Technical Support Group Leader
 Uranium Mill Tailings Remedial
 Action Project Office

CC:
 Roger Shaffer, DEQ, WY

bcc:
 D. Gillen, NRC
 J. Oldham, MK-F
 VPDMS, JEG

CONCURRENCES		
RTG SYMBOL	UMTRA:JS	
INITIALS/SIG	GF	
DATE	01/24/91	
RTG SYMBOL	UMTRA	
INITIALS/SIG	FB	
DATE	1/19/91	
RTG SYMBOL	UMTRA	
INITIALS/SIG	MMatthews	
DATE		
RTG SYMBOL		
INITIALS/SIG		
DATE		
RTG SYMBOL		
INITIALS/SIG		
DATE		
RTG SYMBOL		
INITIALS/SIG		
DATE		
RTG SYMBOL		
INITIALS/SIG		
DATE		



Department of Energy
 Albuquerque Operations Office
 P.O. Box 5400
 Albuquerque, New Mexico 87115

JAN 31 1991

Vicinity Property No. SL-059
 Address: 3363 South 700 West
 Salt Lake City, UT 84119

John Kingston
 3140 South Main Street
 Salt Lake City, UT 84115

Dear Mr. Kingston:

Under the Uranium Mill Tailings Radiation Control Act of 1978 (Public Law 95-604), the U.S. Department of Energy (DOE), with ten percent funding provided by the state, has completed remedial action at the property listed above. Review of the available data indicates your property has been cleared of residual radioactive contamination to the extent required by the Environmental Protection Agency (EPA) Standards (40 CFR Part 192). Therefore, the DOE certifies your property is in compliance with the EPA Standards.

The current status of your property will be recorded by the state on the appropriate property records, per requirements of Public Law 95-604. Records of Uranium Mill Tailings Remedial Action vicinity properties are archived with both the state and the DOE.

Should you have any questions regarding the project or your property, please write to me at the above address or contact Gaeton Falance of my staff at (505) 845-5636 or the Utah Division of Environmental Health (801) 538-6734. Your cooperation in the successful accomplishment of this work has been greatly appreciated.

Sincerely,

Original Signed By

Mark L. Matthews
 Project Manager
 Uranium Mill Tailings Remedial
 Action Project Office

cc: Larry Anderson, DEH, UT
 bcc: D. Gillen, NRC
 J. Oldham, MK-F
 VPDMS, JEG

CONCURRENCES	
RTG SYMBOL	UMTRA; JS
INITIALS/SIG	<i>[Signature]</i>
DATE	01/23/91
RTG SYMBOL	UMTRA....
INITIALS/SIG	FBos... Javal
DATE	1/25/91
RTG SYMBOL	UMTRA.....
INITIALS/SIG	MMatthews
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	

United States Government

Department of Energy

memorandum

Albuquerque Operations Office

DATE: JAN 31 1991

REPLY TO
ATTN OF: UMTRA:G5

SUBJECT: Certification of Vicinity Property No. SL-059, Located at
3363 South 700 West, Salt Lake City, Utah,
From the Uranium Mill Tailings Remedial Action Program

TO: Official Location Folder

In accordance with provisions of the Uranium Mill Tailings Radiation Control Act of 1978 (PL 95-604), the subject property has been evaluated against the Environmental Protection Agency (EPA) Standards for Remedial Action at Inactive Uranium Processing sites (40 CFR Part 192) after the completion of remedial action. The Completion Report was prepared by MK-Ferguson Company, the U.S. Department of Energy (DOE) Remedial Action Contractor.

The DOE has reviewed the Completion Report and associated documentation which indicate the property has been cleared of residual radioactive contamination; therefore, the DOE certifies the property is in compliance with the EPA Standards.

Frank Bosiljevac
 Frank Bosiljevac
 Technical Support Group Leader
 Uranium Mill Tailings Remedial
 Action Project Office

cc:
 Larry Anderson, DEH, UT

bcc:
 D. Gillen, NRC
 J. Oldham, MK-F
 VPIMS, JEG

CONCURRENCES	
RTG SYMBOL	UMTRA:JS
INITIALS/SIG	<i>JS</i>
DATE	GBalance
RTG SYMBOL	UMTRA
INITIALS/SIG	<i>Bosiljevac</i>
DATE	01/23/91
RTG SYMBOL	UMTRA
INITIALS/SIG	<i>MMatthews</i>
DATE	1/1
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	



Department of Energy
 Albuquerque Operations Office
 P.O. Box 5400
 Albuquerque, New Mexico 87115
JAN 31 1991

Vicinity Property No. RT-011
 Address: 921 Rendezvous Road
 Riverton, Wyoming

Vearl Sneed
 1603 10th Street
 Manhattan Beach, CA 90226

Dear Mr. Sneed:

Under the Uranium Mill Tailings Radiation Control Act of 1978 (Public Law 95-604), the U.S. Department of Energy (DOE), with ten percent funding provided by the state, has completed remedial action at the property listed above. Review of the available data indicates your property has been cleared of residual radioactive contamination to the extent required by the Environmental Protection Agency (EPA) Standards (40 CFR Part 192). Therefore, the DOE certifies your property is in compliance with the EPA Standards.

The current status of your property will be recorded by the state on the appropriate property records, per requirements of Public Law 95-604. Records of Uranium Mill Tailings Remedial Action vicinity properties are archived with both the state and the DOE.

Should you have any questions regarding the project or your property, please write to me at the above address or contact Gaeton Falance of my staff at (505) 845-5636 or the Wyoming Department of Environmental Quality at (307) 777-7756. Your cooperation in the successful accomplishment of this work has been greatly appreciated.

Sincerely,

Original Signed By

Mark L. Matthews
 Project Manager
 Uranium Mill Tailings Remedial
 Action Project Office

bcc: cc:
 D. Gillen, NRC Roger Shaffer, DEQ, WY
 J. Oldham, MK-F
 VPDMS, JEG

CONCURRENCES	
RTG SYMBOL	UMTRA:JS
INITIALS/SIG	GF
DATE	01/24/91
RTG SYMBOL	UMTRA
INITIALS/SIG	F.S. Sneed
DATE	1/19/91
RTG SYMBOL	UMTRA
INITIALS/SIG	M. Matthews
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	

United States Government

Department of Energy

Albuquerque Operations Office

memorandum

DATE: JAN 31 1991

REPLY TO
ATTN OF: UMTRA:GF

SUBJECT: Certification of Vicinity Property No. RT-011, Located at
921 Rendezvous Road, Riverton, Wyoming,
From the Uranium Mill Tailings Remedial Action Program

TO: Official Location Folder

In accordance with provisions of the Uranium Mill Tailings Radiation Control Act of 1978 (PL 95-604), the subject property has been evaluated against the Environmental Protection Agency (EPA) Standards for Remedial Action at Inactive Uranium Processing sites (40 CFR Part 192) after the completion of remedial action. The Completion Report was prepared by MK-Ferguson Company, the U.S. Department of Energy (DOE) Remedial Action Contractor.

The DOE has reviewed the Completion Report and associated documentation which indicate the property has been cleared of residual radioactive contamination; therefore, the DOE certifies the property is in compliance with the EPA Standards.

Frank Bosiljevac
Frank Bosiljevac
Technical Support Group Leader
Uranium Mill Tailings Remedial
Action Project Office

cc:
Roger Shaffer, DEQ, WY

bcc:
D. Gillen, NRC
J. Oldham, MK-F
VPDMS, JEG

CONCURRENCES		
RTG SYMBOL	UMTRA:JS	
INITIALS/SIG	GFalance <i>GF</i>	
DATE	01/24/91	
RTG SYMBOL	UMTRA	
INITIALS/SIG	FBosiljevac	
DATE	1/29/91	
RTG SYMBOL	UMTRA	
INITIALS/SIG	MMatthews	
DATE		
RTG SYMBOL		
INITIALS/SIG		
DATE		
RTG SYMBOL		
INITIALS/SIG		
DATE		
RTG SYMBOL		
INITIALS/SIG		
DATE		
RTG SYMBOL		
INITIALS/SIG		
DATE		



Department of Energy
 Albuquerque Operations Office
 P.O. Box 5400
 Albuquerque, New Mexico 87115

JAN 31 1991

Vicinity Property No. GJ-09553
 Address: 2741 "D" Road
 Grand Junction, CO 81501

D. Garlitz
 2741 "D" Road
 Grand Junction, CO 81501

Dear Mr. Garlitz:

Under the Uranium Mill Tailings Radiation Control Act of 1978 (Public Law 95-604), the U.S. Department of Energy (DOE), with ten percent funding provided by the state, has completed remedial action at the property listed above. Review of the available data indicates your property has been cleared of residual radioactive contamination to the extent required by the Environmental Protection Agency (EPA) Standards (40 CFR Part 192). Therefore, the DOE certifies your property is in compliance with the EPA Standards.

The current status of your property will be recorded by the state on the appropriate property records, per requirements of Public Law 95-604. Records of Uranium Mill Tailings Remedial Action vicinity properties are archived with both the state and the DOE.

Should you have any questions regarding the project or your property, please write to me at the above address or contact Gaeton Falance of my staff at (505) 845-5636 or the Colorado Department of Health (303) 248-7164. Your cooperation in the successful accomplishment of this work has been greatly appreciated.

Sincerely,

Original Signed By

Mark L. Matthews
 Project Manager
 Uranium Mill Tailings Remedial
 Action Project Office

cc: G. A. "Bud" Franz, III, CDH, CO

bcc: D. Gillen, NRC
 J. Oldham, MK-F
 VPDMS, JEG

CONCURRENCES	
RTG SYMBOL	UMTRA:JS
INITIALS/SIG	<i>JS</i>
DATE	GBalance..
RTG SYMBOL	01/23/91
INITIALS/SIG	UMTRA....
DATE	<i>FB</i>
RTG SYMBOL	FB
INITIALS/SIG	FB
DATE	1/24/91
RTG SYMBOL	UMTRA.....
INITIALS/SIG	MMatthews.
DATE	1/31/91
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	

United States Government

Department of Energy

memorandum

Albuquerque Operations Office

DATE: JAN 31 1991

REPLY TO
ATTN OF: UMTRA:GF

SUBJECT: Certification of Vicinity Property No. GJ-09553, Located at
2741 "D" Road, Grand Junction, Colorado,
From the Uranium Mill Tailings Remedial Action Program

TO: Official Location Folder

In accordance with provisions of the Uranium Mill Tailings Radiation Control Act of 1978 (PL 95-604), the subject property has been evaluated against the Environmental Protection Agency (EPA) Standards for Remedial Action at Inactive Uranium Processing sites (40 CFR Part 192) after the completion of remedial action. The Completion Report was prepared by MK-Ferguson Company, the U.S. Department of Energy (DOE) Remedial Action Contractor.


The DOE has reviewed the Completion Report and associated documentation which indicate the property has been cleared of residual radioactive contamination; therefore, the DOE certifies the property is in compliance with the EPA Standards.

Frank Bosiljevac
 Frank Bosiljevac
 Technical Support Group Leader
 Uranium Mill Tailings Remedial
 Action Project Office

CC:
 G. A. "Bud" Franz, III, CDH, CO

bcc:
 D. Gillen, NRC
 J. Oldham, MK-F
 VPDMS, JEG

CONCURRENCES		
RTG SYMBOL	UMTRA:JS	
INITIALS/SIG.	<i>JS</i>	
DATE	GBalance...	
RTG SYMBOL	UMTRA.....	
INITIALS/SIG.	FBosiljeva	
DATE	1/28/91	
RTG SYMBOL	UMTRA.....	
INITIALS/SIG.	MMatthews.	
DATE	1/30/91	
RTG SYMBOL		
INITIALS/SIG.		
DATE		
RTG SYMBOL		
INITIALS/SIG.		
DATE		
RTG SYMBOL		
INITIALS/SIG.		
DATE		
RTG SYMBOL		
INITIALS/SIG.		
DATE		



Department of Energy
 Albuquerque Operations Office
 P.O. Box 5400
 Albuquerque, New Mexico 87115

JAN 31 1991

Vicinity Property No. RT-046/047
 Address: Extreme SW Extension of
 South 3rd West Street
 Riverton, Wyoming 82501

D & G Rentals
 John Debortoli &
 Richard Gilpatrick
 South 3rd West Street
 Riverton, Wyoming 82501

Dear Mr. Debortoli & Mr. Gilpatrick:

Under the Uranium Mill Tailings Radiation Control Act of 1978 (Public Law 95-604), the U.S. Department of Energy (DOE), with ten percent funding provided by the state, has completed remedial action at the property listed above. Review of the available data indicates your property has been cleared of residual radioactive contamination to the extent required by the Environmental Protection Agency (EPA) Standards (40 CFR Part 192). Therefore, the DOE certifies your property is in compliance with the EPA Standards.

The current status of your property will be recorded by the state on the appropriate property records, per requirements of Public Law 95-604. Records of Uranium Mill Tailings Remedial Action vicinity properties are archived with both the state and the DOE.

Should you have any questions regarding the project or your property, please write to me at the above address or contact Gaeton Falance of my staff at (505) 845-5636 or the Wyoming Department of Environmental Quality (307) 777-7756. Your cooperation in the successful accomplishment of this work has been greatly appreciated.

Sincerely,

Original Signed By

Mark L. Matthews
 Project Manager
 Uranium Mill Tailings Remedial
 Action Project Office

cc:
 Roger Shaffer, DEQ, WY

bcc:
 D. Gillen, NRC
 J. Oldham, MK-F
 VPDMS, JEG

CONCURRENCES	
RTG SYMBOL	UMTRA:JS
INITIALS/SIG	<i>JS</i>
DATE	GBalance..
DATE	01/24/91
RTG SYMBOL	UMTRA....
INITIALS/SIG	<i>FB</i>
DATE	1/25/91
RTG SYMBOL	UMTRA.....
INITIALS/SIG	MMatthews.
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	

United States Government

Department of Energy

Albuquerque Operations Office

memorandum

DATE: JAN 31 1991


REPLY TO
ATTN OF: UMTRA:GF

SUBJECT: Certification of Vicinity Property No. RT-046/047, Located at
Extreme SW Extension of South 3rd West Street, Riverton, Wyoming,
From the Uranium Mill Tailings Remedial Action Program

TO: Official Location Folder

In accordance with provisions of the Uranium Mill Tailings Radiation Control Act of 1978 (PL 95-604), the subject property has been evaluated against the Environmental Protection Agency (EPA) Standards for Remedial Action at Inactive Uranium Processing sites (40 CFR Part 192) after the completion of remedial action. The Completion Report was prepared by MK-Ferguson Company, the U.S. Department of Energy (DOE) Remedial Action Contractor.

The DOE has reviewed the Completion Report and associated documentation which indicate the property has been cleared of residual radioactive contamination; therefore, the DOE certifies the property is in compliance with the EPA Standards.



Frank Bosiljevac
Technical Support Group Leader
Uranium Mill Tailings Remedial
Action Project Office

CC:
Roger Shaffer, DEQ, WY

bcc:
D. Gillen, NRC
J. Oldham, MK-F
VPDMS, JEG

CONCURRENCES

RTG SYMBOL

UMTRA:JS

INITIALS/SIG *JS*

GBalance...

DATE

01/24/91

RTG SYMBOL

UMTRA

INITIALS/SIG

FB

DATE

1/17/91

RTG SYMBOL

UMTRA

INITIALS/SIG

MMatthews

DATE

RTG SYMBOL

INITIALS/SIG

DATE

RTG SYMBOL

INITIALS/SIG

DATE

RTG SYMBOL

INITIALS/SIG

DATE

RTG SYMBOL

INITIALS/SIG

DATE

RTG SYMBOL

INITIALS/SIG

DATE

RTG SYMBOL

INITIALS/SIG

DATE

RTG SYMBOL

INITIALS/SIG

DATE

RTG SYMBOL

INITIALS/SIG

DATE

RTG SYMBOL

INITIALS/SIG

DATE



Department of Energy
 Albuquerque Operations Office
 P.O. Box 5400
 Albuquerque, New Mexico 87115
 JAN 31 1991

Vicinity Property No. RT-013/059
 Address: 888-892 Rendezvous Road
 Riverton, Wyoming 82501

Joseph Goggles, Sr.
 888-892 Rendezvous Road
 Riverton, Wyoming 82501

Dear Mr. Goggles:

Under the Uranium Mill Tailings Radiation Control Act of 1978 (Public Law 95-604), the U.S. Department of Energy (DOE), with ten percent funding provided by the state, has completed remedial action at the property listed above. Review of the available data indicates your property has been cleared of residual radioactive contamination to the extent required by the Environmental Protection Agency (EPA) Standards (40 CFR Part 192). Therefore, the DOE certifies your property is in compliance with the EPA Standards.

The current status of your property will be recorded by the state on the appropriate property records, per requirements of Public Law 95-604. Records of Uranium Mill Tailings Remedial Action vicinity properties are archived with both the state and the DOE.

Should you have any questions regarding the project or your property, please write to me at the above address or contact Gaeton Falance of my staff at (505) 845-5636 or the Wyoming Department of Environmental Quality (307) 777-7756. Your cooperation in the successful accomplishment of this work has been greatly appreciated.

Sincerely,

Original Signed By

Mark L. Matthews
 Project Manager
 Uranium Mill Tailings Remedial
 Action Project Office

cc:
 Roger Shaffer, DEQ, WY

bcc:
 D. Gillen, NRC
 J. Oldham, MK-F
 VPDMs, JEG

CONCURRENCES	
RTG SYMBOL	UMTRA:JS
INITIALS/SIG	<i>JS</i>
DATE	01/24/91
RTG SYMBOL	UMTRA
INITIALS/SIG	FBasiljeva
DATE	1/18/91
RTG SYMBOL	UMTRA
INITIALS/SIG	MMatthews
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	

United States Government

Department of Energy

Albuquerque Operations Office

memorandum

DATE: JAN 31 1991

REPLY TO
ATTN OF: UMTRA:GFSUBJECT: Certification of Vicinity Property No. RT-013/059, Located at
888-892 Rendevious Road, Riverton, Wyoming,
From the Uranium Mill Tailings Remedial Action Program

TO: Official Location Folder

In accordance with provisions of the Uranium Mill Tailings Radiation Control Act of 1978 (PL 95-604), the subject property has been evaluated against the Environmental Protection Agency (EPA) Standards for Remedial Action at Inactive Uranium Processing sites (40 CFR Part 192) after the completion of remedial action. The Completion Report was prepared by MK-Ferguson Company, the U.S. Department of Energy (DOE) Remedial Action Contractor.

The DOE has reviewed the Completion Report and associated documentation which indicate the property has been cleared of residual radioactive contamination; therefore, the DOE certifies the property is in compliance with the EPA Standards.

Frank Bosiljevac
Frank Bosiljevac
Technical Support Group Leader
Uranium Mill Tailings Remedial
Action Project Office

cc:
Roger Shaffer, DEQ, WY

bcc:
D. Gillen, NRC
J. Oldham, MK-F
VPDMS, JEG

CONCURRENCES	
RTG SYMBOL	UMTRA:JS
INITIALS/SIG	<i>JS</i>
DATE	GBalance...
RTG SYMBOL	01/24/91
INITIALS/SIG	UMTRA
DATE	FBosiljevac
RTG SYMBOL	1/24/91
INITIALS/SIG	UMTRA
DATE	MMatthews
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	



Department of Energy
 Albuquerque Operations Office
 P.O. Box 5400
 Albuquerque, New Mexico 87115

JAN 31 1991

Vicinity Property No. RT-096
 Address: South 3rd West
 and River Road
 Riverton, WY 82501

Bad Water Lines
 South 3rd West
 and River Road
 Riverton, Wyoming 82501

Dear Sir:

Under the Uranium Mill Tailings Radiation Control Act of 1978 (Public Law 95-604), the U.S. Department of Energy (DOE), with ten percent funding provided by the state, has completed remedial action at the property listed above. Review of the available data indicates your property has been cleared of residual radioactive contamination to the extent required by the Environmental Protection Agency (EPA) Standards (40 CFR Part 192). Therefore, the DOE certifies your property is in compliance with the EPA Standards.

The current status of your property will be recorded by the state on the appropriate property records, per requirements of Public Law 95-604. Records of Uranium Mill Tailings Remedial Action vicinity properties are archived with both the state and the DOE.

Should you have any questions regarding the project or your property, please write to me at the above address or contact Gaeton Falance of my staff at (505) 845-5636 or the Wyoming Department of Environmental Quality (307) 777-7756. Your cooperation in the successful accomplishment of this work has been greatly appreciated.

Sincerely,

Original Signed By

Mark L. Matthews
 Project Manager
 Uranium Mill Tailings Remedial
 Action Project Office

cc:
 Roger Shaffer, DEQ, WY

CONCURRENCES	
RTG SYMBOL	UMTRA:JS
INITIALS/SIG.	JS
DATE	01/25/91
RTG SYMBOL	UMTRA
INITIALS/SIG.	FBasiljeva
DATE	1/28/91
RTG SYMBOL	UMTRA
INITIALS/SIG.	MMatthews
DATE	
RTG SYMBOL	
INITIALS/SIG.	
DATE	
RTG SYMBOL	
INITIALS/SIG.	
DATE	
RTG SYMBOL	
INITIALS/SIG.	
DATE	
RTG SYMBOL	
INITIALS/SIG.	
DATE	

bcc:
 D. Gillen, NRC
 J. Oldham, MK-E

United States Government

Department of Energy

Albuquerque Operations Office

memorandum

DATE: JAN 31 1991


REPLY TO
ATTN OF: UMTRA:GF

SUBJECT: Certification of Vicinity Property No. RT-096, Located at
South 3rd West and River Road, Riverton, Wyoming,
From the Uranium Mill Tailings Remedial Action Program

TO: Official Location Folder

In accordance with provisions of the Uranium Mill Tailings Radiation Control Act of 1978 (PL 95-604), the subject property has been evaluated against the Environmental Protection Agency (EPA) Standards for Remedial Action at Inactive Uranium Processing sites (40 CFR Part 192) after the completion of remedial action. The Completion Report was prepared by MK-Ferguson Company, the U.S. Department of Energy (DOE) Remedial Action Contractor.

The DOE has reviewed the Completion Report and associated documentation which indicate the property has been cleared of residual radioactive contamination; therefore, the DOE certifies the property is in compliance with the EPA Standards.


Frank Bosiljevac
Technical Support Group Leader
Uranium Mill Tailings Remedial
Action Project Office

CC:
Roger Shaffer, DEQ, WY

CONCURRENCES	
RTG SYMBOL	UMTRA:JS
INITIALS/SIG	GF
DATE	01/25/91
RTG SYMBOL	UMTRA....
INITIALS/SIG	FBosiljeva
DATE	/ /
RTG SYMBOL	UMTRA.....
INITIALS/SIG	MMatthews
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	

bcc:
D. Gillen, NRC
J. Oldham, MK-F

United States Government

Department of Energy

Albuquerque Operations Office

memorandum

DATE: JAN 31 1991


REPLY TO
ATTN OF: UMTRA:GF

SUBJECT: Certification of Vicinity Property No. DU-202, Located at Gateway Park, U.S. Highway 550/160, Durango, Colorado, From the Uranium Mill Tailings Remedial Action Program

TO: Official Location Folder

In accordance with provisions of the Uranium Mill Tailings Radiation Control Act of 1978 (PL 95-604), the subject property has been evaluated against the Environmental Protection Agency (EPA) Standards for Remedial Action at Inactive Uranium Processing sites (40 CFR Part 192) after the completion of remedial action. The Completion Report was prepared by MK-Ferguson Company, the U.S. Department of Energy (DOE) Remedial Action Contractor.

The DOE has reviewed the Completion Report and associated documentation which indicate the property has been cleared of residual radioactive contamination; therefore, the DOE certifies the property is in compliance with the EPA Standards.




Frank Bosiljevac
 Technical Support Group Leader
 Uranium Mill Tailings Remedial
 Action Project Office

cc:
 G. A. "Bud" Franz, III, CDH, CO

bcc:
 D. Gillen, NRC
 J. Oldham, MK-F
 VPDMS, JEG

CONCURRENCES	
RTG SYMBOL	UMTRA:JS
INITIALS/SIG	GF
DATE	01/23/91
RTG SYMBOL	UMTRA...
INITIALS/SIG	FBosiljevac
DATE	/ /
RTG SYMBOL	UMTRA.....
INITIALS/SIG	MMatthews.
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	



Department of Energy
 Albuquerque Operations Office
 P.O. Box 5400
 Albuquerque, New Mexico 87115
 JAN 31 1991

Vicinity Property No. RT-066
 Address: 140 Goes in
 Lodge Road
 Riverton, Wyoming 82501

Chemical Marketing Services
 140 Goes in Lodge Road
 Riverton, Wyoming 82501

Dear Sir:

Under the Uranium Mill Tailings Radiation Control Act of 1978 (Public Law 95-604), the U.S. Department of Energy (DOE), with ten percent funding provided by the state, has completed remedial action at the property listed above. Review of the available data indicates your property has been cleared of residual radioactive contamination to the extent required by the Environmental Protection Agency (EPA) Standards (40 CFR Part 192). Therefore, the DOE certifies your property is in compliance with the EPA Standards.

The current status of your property will be recorded by the state on the appropriate property records, per requirements of Public Law 95-604. Records of Uranium Mill Tailings Remedial Action vicinity properties are archived with both the state and the DOE.

Should you have any questions regarding the project or your property, please write to me at the above address or contact Gaeton Falance of my staff at (505) 845-5636 or the Wyoming Department of Environmental Quality (307) 777-7756. Your cooperation in the successful accomplishment of this work has been greatly appreciated.

Sincerely,

Original Signed By

Mark L. Matthews
 Project Manager
 Uranium Mill Tailings Remedial
 Action Project Office

cc:
 Roger Shaffer, DEQ, WY

bcc:
 D. Gillen, NRC
 J. Oldham, MK-F

CONCURRENCES	
RTG SYMBOL	UMTRA:JS
INITIALS/SIG	GBF
DATE	GBalance...
RTG SYMBOL	01/25/91
INITIALS/SIG	UMTRA
DATE	EB
RTG SYMBOL	7/15/91
INITIALS/SIG	UMTRA
DATE	MMatthews
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	

United States Government

Department of Energy


memorandum

Albuquerque Operations Office

DATE: JAN 31 1991
REPLY TO: UMTRA:GF
ATTN OF:
SUBJECT: Certification of Vicinity Property No. RT-066, Located at
140 Goes in Lodge Road, Riverton, Wyoming,
From the Uranium Mill Tailings Remedial Action Program
TO: Official Location Folder


In accordance with provisions of the Uranium Mill Tailings Radiation Control Act of 1978 (PL 95-604), the subject property has been evaluated against the Environmental Protection Agency (EPA) Standards for Remedial Action at Inactive Uranium Processing sites (40 CFR Part 192) after the completion of remedial action. The Completion Report was prepared by MK-Ferguson Company, the U.S. Department of Energy (DOE) Remedial Action Contractor.

The DOE has reviewed the Completion Report and associated documentation which indicate the property has been cleared of residual radioactive contamination; therefore, the DOE certifies the property is in compliance with the EPA Standards.



Frank Bosiljevac
Technical Support Group Leader
Uranium Mill Tailings Remedial
Action Project Office

cc:
Roger Shaffer, DEQ, WY



Department of Energy
 Albuquerque Operations Office
 P.O. Box 5400
 Albuquerque, New Mexico 87115

JAN 31 1991

Vicinity Property No. SL-018S/114
 Address: Roper Switch Yard
 Salt Lake City, Utah

Mr. Ramon Hall
 U.S. Nuclear Regulatory Commission
 Uranium Recovery Field Office
 P.O. Box 25325
 Denver, Colorado 80225

Dear Mr. Hall:

In accordance with the Uranium Mill Tailings Radiation Control Act of 1978 (Public Law 95-604), the Environmental Protection Agency (EPA) Standards (40 CFR Part 192), and the Memorandum of Understanding between U.S. Department of Energy (DOE) and the U.S. Nuclear Regulatory Commission (NRC) (GMO04-85AL26037), two copies of the Vicinity Property Completion Report for the above property are submitted for NRC certification concurrence. Please note the NRC has previously concurred in the application of supplemental standards as presented within the Radiological Engineering Assessment. Also enclosed to aid in the review are the NRC Review form and a copy of the Vicinity Property Certification Summary and Decision.

Should you have any questions, contact Gaeton Falance of my staff at (505) 845-5636 or FTS 845-5636.

Sincerely,

Original Signed By

Mark L. Matthews
 Project Manager
 Uranium Mill Tailings Remedial
 Action Project Office

Enclosures

cc:
 Larry Anderson, DH, UT

9102130056 910131
 FDR WASTE
 WM-39
 FDR

bcc:
 D. Gillen, NRC
 J. Oldham, MK-F
 VPDMS, JEG

CONCURRENCES	
RTG SYMBOL	UMTRA:JS.
INITIALS/SIG	GFalance... <i>GF</i>
DATE	01/24/91
RTG SYMBOL	UMTRA
INITIALS/SIG	FBosiljeva
DATE	1/28/91
RTG SYMBOL	UMTRA
INITIALS/SIG	MMatthews.
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	
RTG SYMBOL	
INITIALS/SIG	
DATE	