



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

MAR 1 1983

Report No. 50-335/83-01

Docket No. 50-335

License No. DPR-67

Licensee: Florida Power and Light Company
9250 West Flagler Street
Miami, FL 33101

Facility Name: St. Lucie 1

Inspection at: Ft. Pierce, Florida

Inspection conducted: January 6, 1983

Date of Last Physical Security Inspection Visit: December 13-17, 1982

Type of Inspection: Unannounced Physical Security

Inspector:

C. D. Perny
C. D. Perny, Physical Security Inspector

01-17-83
Date Signed

Approved by:

D. R. McGuire
D. R. McGuire, Chief, Physical Security Section
Safeguards Branch, Division of Emergency Preparedness
and Material Safety Programs

1/17/83
Date Signed

Inspection Summary

Areas Inspected: Included review of the physical security plan and implementing procedures relative to access control, detection aids, and alarm stations in response to a licensee reported incident.

The inspection involved eight inspector hours on site by one NRC inspector.

Results: The licensee was found to be in compliance with NRC requirements within the three areas examined during the inspection except for the following item.

Failure to have adequate compensatory procedures for access control activities and alarm monitoring.

8304280162 830301
PDR ADOCK 05000335
G PDR

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.